ENQUIRY SITE VISIT REPORT

NIHVA
NIHVA TECHNOLOGIES PVT. LTD.

Purpose of visit	:- New Enquiry Site Visit Report	Date :-	28/10/25
	:-	Format :-	NIHVA-PRJ-F-01
Client	:- KLE Hospital		
Project	:-		
Site Location	:- Hubali		
Contact Person Name	:-		
Product Name	:- Motorised rolling shutter		
product quantity	:-		
Sales Person Name	:-		
Attended by	:- Abhishek Ardalkar		

Actual Site Condition :-

1. Main entry (w) 12900 x (h) 2750 - 1 NOS
2. Main entry (left side - L corner)
   (w) 2500 x (h) 2750 - 1 NOS
3. Main entry (Right side) -
   (w) 2700 x 2390 - 1 NOS

Solutions/Suggestion Readiness site :-

4. Skill lab (w) 3100 x (h) 2350 - 1 NOS
5. Library (w) 1850 x (h) 2750 - 1 NOS
6. Library (w) 5800 x (h) 2800 - 1 NOS

Remark :-

1. Puff Panel cutting in client scope
2. All structure work (if required) in client scope
3. High plex board cutting in client scope.

Nihva Representative :- Abhishek Ardalkar	Client Representive :- Hiremani Patil
Signature :- Abhishek Ardalkar	Signature :-
Date :- 28/10/25	Date :- 29/10/25

NIHVA
"Solutions for People People for Solutions"

Samir Plaza, 1st Floor, G-Block, Thermax Chowk, Chinchwad, Pune - 411019.
(+91 2066 3040 33 +91 85 51091 333 sales@nihva.com www.nihva.com

* Back side

Scanned with OKEN Scanner

⑦ ~~[illegible]~~ Medical Area (Main hospital)

~~[illegible]~~


~~[illegible]~~

① (w) 2320 x (h) 2400 = 2 NOS

② (w) 2625 x (h) 2100 = 4 NOS

28/10/25

* College Main Entrance – (W) 12900 × (H) 2750 – 1 NOS




28/10/25

① High Pick board removed in client scope
② Outside fixing or inside fixing → client confirmation pending.
③ Structure in client scope.
④ Motor RFS

Scanned with OKEN Scanner

Main entrance (left side) (L corner) (W) 2500 x (H) 2750 — 1 Nos




1. High lev board removed in client scope
2. Outside fixing or Inside fixing → client confirmation pending
3. Structure in client scope
4. Motor — LHS

28/10/25

Scanned with OKEN Scanner

* College Main Entrance (Right side) — Inside Fixing




25/10/25

(w) 2700 x (h) 2390 - 1 Nos

① High lex board removed in client scope.
② Structure in client scope ③ Back side gap close in client scope.

Scanned with OKEN Scanner


Skill Lab — (a) 3100 × (b) 2350 - 1 NOS
(Fixing outside)



Existing high flex board remove in client scope


28/10/25

① Library — (w) 1850 × (h) 2750 = 1 Nos



① Right side putt panel & Top side putt panel cutting in client scope
② Structure in client scope.
③ Fixing out side.
④ Motor - LHS.

② Library — (w) 5800 × (h) 2800 = 1 Nos




28/10/25

Shop area – (Main Hospital – Medical Area)

① required structure in client scope

② High flex board or Fritcher sheet remove in client scope.



① (w) 5650 x (h) 2100 = 2 NOS

② (w) 5025 x (h) 2100 = 1 NOS

↳ qty split → (w) 2320 x (h) 2100 = 2 NOS

↳ qty split → (w) 2625 x (h) 2100 = 4 NOS

28/10/25

Scanned with OKEN Scanner