NIHVA
NIHVA Technologies Pvt. Ltd.

PRE DISPATCH INSPECTION REPORT

Format no.: NIHVA- QA-F-07
Rev. no.: 00
Rev date:
Date of origin: 01.01.2017

Client Name- Tata Motors Limited | **Report No-**-SO/23-24/060(1)

Project Name- NTPL-215 | **Location-** NIHVA MANUFACTURING UNIT | **Date-10-02-2024**

Product Name- 2 Hrs Fire Rated Rolling Shutter (W 4000 mm X H 4000 mm) | **Qty-**02 NOS

Sr.No	Part Name	Drawing No	Dimension In mm	Qty per Product	Observation			Instrument used	Remark
					1	2	3		
1	Curtain Length	NIHVA-23-24-CLT-102	4150 ± 5	58	4147	4150	_	Steel Tape	OK
2	Curtain width	NIHVA-23-24-CLT-102	77 ± 1.5		87.71	87.79	87.7	Digital Vernier caliper	NOT OK
3	Curtain Thickness	NIHVA-23-24-CLT-102	1.2 ± 0.2		1.21	1.21	1.2	Digital Micrometer	OK
4	Curtain Profile	NIHVA-23-24-CLT-102	Curved		OK	OK	OK	Visual	OK
5	Hood cover (LxWxH)	NIHVA-23-24-CLT-102	600x450	1	Loose patti			Steel Tape	NOT OK
6	Hood cover thickness	NIHVA-23-24-CLT-102	0.9		0.883	0.952	0.922	Digital Micrometer	OK
7	Roller Length	NIHVA-23-24-CLT-102	4060	1	4064	4063	_	Steel Tape	OK
8	Roller dia.	NIHVA-23-24-CLT-102	114 ± 2		113.8	113.88	_	Digital Vernier caliper	OK
9	M.S. Bottom length	NIHVA-23-24-CLT-102	4150 ± 5	1	4147	4150	_	Steel Tape	OK
10	M.S. Bottom width	NIHVA-23-24-CLT-102	120 ± 1.2		60.68	60.72	_	Digital Vernier caliper	NOT OK
11	M.S. Bottom thickness	NIHVA-23-24-CLT-102	1.2 sheet bend		OK	OK	_	Visual	OK
12	Guide length	NIHVA-23-24-CLT-102	4120	1	4114	4118	_	Steel Tape	OK
13	Guide thickness	NIHVA-23-24-CLT-102	3 ± 0.2		1.6	1.582	_	Digital Micrometer	NOT OK
14	M.S. Bracket (LxW)	NIHVA-23-24-CLT-102	600x450	1	380X380	380X380	_	Steel Tape	NOT OK
15	M.S. Bracket thickness	NIHVA-23-24-CLT-102	_		Not measured			_	_
16	Motor -SK Motors		1 Phase, Capacity- 500kg, 230V, 50Hz						OK
17	Surface Finish		RAL-7012	_	OK	OK	_	Visual	OK
18	Coating thickness		70-90	_	78.6µ	87.2µ	71.9µ	DFT Meter	OK
19	Product name plate				Missing				NOT OK
20	Test certificate(BS 476 Part 22 & MS 1073 Part 3 1988)				Not available				_

Remark- All Material Are visually & dimensionally found ok

Note-1)All dimensions are in mm 2) Tolerance used as per DIN ISO 2768 - mk

NIHVA TECHNOLOGIES PVT. LTD. PUNE

Inspected By- Maruti Yamgar

Approved By- Amit Kurhade

NIHVA
NIHVA Technologies Pvt. Ltd.

PRE DISPATCH INSPECTION REPORT

Format no.: NIHVA- QA-F-07
Rev. no.: 00
Rev date:
Date of origin: 01.01.2017

Client Name- Tata Motors Limited | **Report No--**SO/23-24/060(2)

Project Name- NTPL-215 | **Location-** NIHVA MANUFACTURING UNIT | **Date-17-02-2024**

Product Name- 2 Hrs Fire Rated Door (W 1000 mm X H 2500 mm) | **Qty-**02 NOS

Sr.No	Part Name	Drawing No	Dimension In mm	Qty per Product	Observation			Instrument used	Remark
					1	2	3		
1	Total height	NIHVA/23-24/CLT/101	2500 ± 8	1	2501	2502	–	Steel Tape	OK
2	Total width	NIHVA/23-24/CLT/101	1000 ± 4	1	1004	1004	–	Steel Tape	OK
3	Dimension	NIHVA/23-24/CLT/101	1374 ± 6	1	1370	1372	–	Steel Tape	OK
4	Dimension	NIHVA/23-24/CLT/101	915 ± 4	1	918	919	_	Steel Tape	OK
5	Window length Outer	NIHVA/23-24/CLT/101	300 ± 2.5	1	330	330	_	Steel Tape	NOT OK
6	Window width Outer	NIHVA/23-24/CLT/101	200 ± 2.5	1	230	230	_	Steel Tape	NOT OK
7	Dimension	NIHVA/23-24/CLT/101	107 ± 1.5	2	110	110	_	Steel Tape	NOT OK
8	Dimension	NIHVA/23-24/CLT/101	50 ± 1.5	2	49	49	_	Steel Tape	OK
9	Dimension	NIHVA/23-24/CLT/101	40 ± 1.5	2	40	40	_	Steel Tape	OK
10	Dimension	NIHVA/23-24/CLT/101	60 ± 1.5	2	59	59	_	Steel Tape	OK
11	Dimension	NIHVA/23-24/CLT/101	47 ± 1.5	1	47	47	_	Steel Tape	OK
12	Hinges position	NIHVA/23-24/CLT/101	4 nos	4	Not equally distance as per drawing			Visual	NOT OK
13	Hole fast	NIHVA/23-24/CLT/101	5 nos	5	4	4	_	Visual	NOT OK
14	Hinges	NIHVA/23-24/CLT/101	Bought out material	4	4	4	_	Visual	OK
15	Panic bar	NIHVA/23-24/CLT/101	Bought out material	1	_	_	_	Bought out material	OK
16	D-handle	NIHVA/23-24/CLT/101	Bought out material	1	_	_	_	Bought out material	OK
17	Glass	NIHVA/23-24/CLT/101	Bought out material	1	_	_	_	Bought out material	OK
18	Door closer	NIHVA/23-24/CLT/101	Bought out material	1	_	_	_	Bought out material	OK
19	Product name plate			NOT AVAILABLE					NOT OK
Test certificate(BS 476 Part 22 & MS 1073 Part 3 1988)				Not available					_

Remark- All Material Are visually & dimensionally found ok

Note-1)All dimensions are in mm 2) Tolerance used as per DIN ISO 2768 - mk

NIHVA TECHNOLOGIES PVT LTD. PUNE

Inspected By- Maruti Yamgar

Approved By- Amit Kurhade