FORM – 11

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

(See Rule 62 & 64)

1	Name of the Occupier	:	**MR. VIJAY TARAK**
2	Name and address of the Factory	:	NIHVA TECHNOLOGIES PVT. LTD. 187, G BLOCK, MIDC, THARMAX CHOWK, CHICHWAD, PUNE
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	:	Chain Pulley Block 1. Chain Pulley Block, Cap. 3 Ton, Make- Tuff, Sr./ID No. CPB-01, Loca. Work Shop
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory.	:	Record not available.
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	:	Record not available. RECORD NOT AVAILABLE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:	Not applicable.
	a) Enclosure of hoistway or liftway.	:	Not applicable.
	b) Landing Gates and Cage gate(s).	:	Not applicable.
	c) Interlocks on the landing gates and cage gate(s).	:	Not applicable.
	d) Other gates fastenings.	:	Not applicable.
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoistway or liftway.	:	Not applicable.
	f) Overrunning devices.	:	Not applicable.
	g) Suspension ropes or chains and their attachments.	:	Not applicable.
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	:	Not applicable.
	i) Brakes	:	Not applicable.
	j) Work of spur gearing.	:	Not applicable.
	k) Other electrical equipment.	:	Not applicable.
	l) Other parts.	:	Not applicable.

FORM – 11

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

(See Rule 62 & 64)

5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.		Record not available.
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	:	Not applicable.
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	:	No defect found.
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).		At the time of examination/test was found ok and satisfactory. Shall be properly maintained in safe working condition.

I/We certify that on **24-11-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

Signature of Competent Person :

Preetam Dattatray Deshpande

Digitally signed by Preetam Dattatray Deshpande

Name of Competent Person		PREETAM DESHPANDE, CPC NO.MS/DISH/CPC/D-065
Qualification		D.M.E., ADIS, B. E. (MECH.)
Address		Neel-Padma, Build.No.5, Flat No.9, Savarkarnagar, Manikbag, Sinhgad Road,
Date		**24-11-2023**

FORM – 11

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

(See Rule 62 & 64)

1	Name of the Occupier	:	**MR. VIJAY TARAK**
2	Name and address of the Factory	:	NIHVA TECHNOLOGIES PVT. LTD. 187, G BLOCK, MIDC, THARMAX CHOWK, CHICHWAD, 0 PUNE
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	:	Pallet Truck 2. Hand Pallet Truck, Cap. 2500 Kg, Make-Hundai, Sr./ID No. 21018424, HPT-01, Loca. Work Shop
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory.	:	Record not available.
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	:	Record not available. RECORD NOT AVAILABLE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:	Not applicable.
	a) Enclosure of hoistway or liftway.	:	Not applicable.
	b) Landing Gates and Cage gate(s).	:	Not applicable.
	c) Interlocks on the landing gates and cage gate(s).	:	Not applicable.
	d) Other gates fastenings.	:	Not applicable.
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoistway or liftway.	:	Not applicable.
	f) Overrunning devices.	:	Not applicable.
	g) Suspension ropes or chains and their attachments.	:	Not applicable.
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	:	Not applicable.
	i) Brakes	:	Not applicable.
	j) Work of spur gearing.	:	Not applicable.
	k) Other electrical equipment.	:	Not applicable.
	l) Other parts.	:	Not applicable.

FORM – 11

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

(See Rule 62 & 64)

5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.		Record not available.
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	:	Not applicable.
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	:	No defect found.
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).		At the time of examination/test was found ok and satisfactory. Shall be properly maintained in safe working condition.

I/We certify that on **24-11-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

Signature of Competent Person :

Preetam Dattatray Deshpande

Digitally signed by Preetam Dattatray Deshpande

Name of Competent Person		PREETAM DESHPANDE, CPC NO.MS/DISH/CPC/D-065
Qualification		D.M.E., ADIS, B. E. (MECH.)
Address		Neel-Padma, Build.No.5, Flat No.9, Savarkarnagar, Manikbag, Sinhgad Road,
Date		**24-11-2023**

FORM – 11

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

(See Rule 62 & 64)

1	Name of the Occupier	:	**MR. VIJAY TARAK**
2	Name and address of the Factory	:	NIHVA TECHNOLOGIES PVT. LTD. 187, G BLOCK, MIDC, THARMAX CHOWK, CHICHWAD, 0 PUNE
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	:	Pallet Truck 3. Hand Pallet Truck, Cap. 2500 Kg, Make-Hundai, Sr./ID No. HPT-02, Loca. Work Shop
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory.	:	Record not available.
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	:	Record not available. RECORD NOT AVAILABLE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:	Not applicable.
	a) Enclosure of hoistway or liftway.	:	Not applicable.
	b) Landing Gates and Cage gate(s).	:	Not applicable.
	c) Interlocks on the landing gates and cage gate(s).	:	Not applicable.
	d) Other gates fastenings.	:	Not applicable.
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoistway or liftway.	:	Not applicable.
	f) Overrunning devices.	:	Not applicable.
	g) Suspension ropes or chains and their attachments.	:	Not applicable.
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	:	Not applicable.
	i) Brakes	:	Not applicable.
	j) Work of spur gearing.	:	Not applicable.
	k) Other electrical equipment.	:	Not applicable.
	l) Other parts.	:	Not applicable.

FORM – 11

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

(See Rule 62 & 64)

5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.		Record not available.
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	:	Not applicable.
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	:	No defect found.
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).		At the time of examination/test was found ok and satisfactory. Shall be properly maintained in safe working condition.

I/We certify that on **24-11-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

Signature of Competent Person :

Preetam Dattatray Deshpande

Digitally signed by Preetam Dattatray Deshpande

Name of Competent Person		PREETAM DESHPANDE, CPC NO.MS/DISH/CPC/D-065
Qualification		D.M.E., ADIS, B. E. (MECH.)
Address		Neel-Padma, Build.No.5, Flat No.9, Savarkarnagar, Manikbag, Sinhgad Road,
Date		**24-11-2023**