NIHVA
NIHVA TECHNOLOGIES PVT. LTD.

Dock leveler Check List

Test Report.

07.06.18

Client Name & Location	:-	IKEA INDIA PVT LTD	
Dock Model.No.	:-	—	Dock Serial No.:- NDL 72, 73, 74.
Dock size	:-	2200 x 2450 x 550	

Sr.No	INSPECTION POINTS	DESCRIPTION	YES	NO	NA
1	Size	Check the size as per drawing	✓		
2	Operation	Check for the smooth/ noisefree opearation	✓		
3	Leakages	Check the deck and lip cylinders for any leakage		✓	
4	Oil level	Ckeck the oil level	✓		
5	Lip Hinges	Inspect Lip hinges for friction and allignment	✓		
6	Platform Condition	Check the flatness and squareness	✓		
7	Rear Hinges	Inspect rear hinges for frictionless operation	✓		
8	Safety plates	Check that all capacity, safety, identification plates, etc. Are attached and legible.	✓		
9	Paint	Check the paint quality	✓		
10	Power pack inspection	Check the leakage and operation of Power pack	✓		

Remarks (if any) :-

NIHVA Inspection /Maintanance person Name :- Vikrant Jadhav.

Sign of Inspection / maintanance person :- Vikrant

User/Client Shift Engg. / Manager Name & Sign :- —

NIHVA

NIHVA TECHNOLOGIES PVT. LTD.

Dock leveler Check List

Test Report

09.06.18

Client Name & Location :- IKEA INDIA PVT LTD

Dock Model.No. :- Dock Serial No.:- NDL75, 76, 77, 78.

Dock size :- 2200 x 2400 x 550.

Sr.No	INSPECTION POINTS	DESCRIPTION	YES	NO	NA
1	Size	Check the size as per drawing	✓		
2	Operation	Check for the smooth/ noisefree opearation	✓		
3	Leakages	Check the deck and lip cylinders for any leakage		✓	
4	Oil level	Ckeck the oil level	✓		
5	Lip Hinges	Inspect Lip hinges for friction and allignment	✓		
6	Platform Condition	Check the flatness and squareness	✓		
7	Rear Hinges	Inspect rear hinges for frictionless operation	✓		
8	Safety plates	Check that all capacity, safety, identification plates, etc. Are attached and legible.	✓		
9	Paint	Check the paint quality	✓		
10	Power pack inspection	Check the leakage and operation of Power pack	✓		

Remarks (if any) :-

NIHVA Inspection /Maintanance person Name :- Vikrant Jadhav

Sign of Inspection / maintanance person :- Vikrant

User/Client Shift Engg. / Manager Name & Sign :-

NIHVA

NIHVA TECHNOLOGIES PVT. LTD.

Dock leveler Check List

Test Report 27.06.18.

Client Name & Location :- IKEA INDIA PVT LTD

Dock Model.No. :- Dock Serial No.:- NDL 79 to 82.

Dock size :- 2200 x 2450 x 550

Sr.No	INSPECTION POINTS	DESCRIPTION	YES	NO	NA
1	Size	Check the size as per drawing	✓		
2	Operation	Check for the smooth/ noisefree opearation	✓		
3	Leakages	Check the deck and lip cylinders for any leakage		✓	
4	Oil level	Ckeck the oil level	✓		
5	Lip Hinges	Inspect Lip hinges for friction and allignment	✓		
6	Platform Condition	Check the flatness and squareness	✓		
7	Rear Hinges	Inspect rear hinges for frictionless operation	✓		
8	Safety plates	Check that all capacity, safety, identification plates, etc. Are attached and legible.	✓		
9	Paint	Check the paint quality	✓		
10	Power pack inspection	Check the leakage and operation of Power pack	✓		

Remarks (if any) :-

NIHVA Inspection /Maintanance person Name :- Vikaant Jadhav

Sign of Inspection / maintanance person :- Vikaant

User/Client Shift Engg. / Manager Name & Sign :-

NIHVA

NIHVA TECHNOLOGIES PVT. LTD.

Dock leveler Check List

Test Report

09.07.18

Client Name & Location :- IKEA INDIA PVT LTD

Dock Model.No. :- Dock Serial No.:- NDL83, 84, 85.

Dock size :- 2200 X 2450 X 550.

Sr.No	INSPECTION POINTS	DESCRIPTION	YES	NO	NA
1	Size	Check the size as per drawing	✓		
2	Operation	Check for the smooth/ noisefree opearation	✓		
3	Leakages	Check the deck and lip cylinders for any leakage		✓	
4	Oil level	Ckeck the oil level	✓		
5	Lip Hinges	Inspect Lip hinges for friction and allignment	✓		
6	Platform Condition	Check the flatness and squareness	✓		
7	Rear Hinges	Inspect rear hinges for frictionless operation	✓		
8	Safety plates	Check that all capacity, safety, identification plates, etc. Are attached and legible.	✓		
9	Paint	Check the paint quality	✓		
10	Power pack inspection	Check the leakage and operation of Power pack	✓		

Remarks (if any) :-

NIHVA Inspection /Maintanance person Name :- Vikrant Jadhav

Sign of Inspection / maintanance person :- Vikrant

User/Client Shift Engg. / Manager Name & Sign :-

NIHVA

NIHVA TECHNOLOGIES PVT. LTD.

Dock leveler Check List

Test Report. 24.07.18

Client Name & Location	:-	IKEA INDIA PVT LTD	
Dock Model.No.	:-	—	Dock Serial No.:- NDL 86,87,88,89.
Dock size	:-	2200 X 2450 X 550.	

Sr.No	INSPECTION POINTS	DESCRIPTION	YES	NO	NA
1	Size	Check the size as per drawing	✓		
2	Operation	Check for the smooth/ noisefree opearation	✓		
3	Leakages	Check the deck and lip cylinders for any leakage		✓	
4	Oil level	Ckeck the oil level	✓		
5	Lip Hinges	Inspect Lip hinges for friction and allignment	✓		
6	Platform Condition	Check the flatness and squareness	✓		
7	Rear Hinges	Inspect rear hinges for frictionless operation	✓		
8	Safety plates	Check that all capacity, safety, identification plates, etc. Are attached and legible.	✓		
9	Paint	Check the paint quality	✓		
10	Power pack inspection	Check the leakage and operation of Power pack	✓		

Remarks (if any) :-

NIHVA Inspection /Maintanance person Name :-	Vikant Jadhav
Sign of Inspection / maintanance person :-	Vikant
User/Client Shift Engg. / Manager Name & Sign :-	