

# JK Lakshmi Cement - Wagon Damage Report

Report Generated on: February 01, 2025

## Wagon Damage Report – JK Lakshmi Cement

- This report highlights damages detected in railway wagons during inspection before loading.
- Each wagon has been analyzed for cracks, rust, dents, and structural wear.
- The findings provide insights for necessary maintenance and operational improvements.

*"Ensuring wagon integrity is crucial for uninterrupted logistics. This report provides a clear evaluation of detected issues."*



**Wagon Number: 1**

Cement residue: 3 Side crack: 6 **Total damage count: 9**



**Wagon Number: 2**

Cement residue: 2 Side crack: 3 **Total damage count: 5**



**Wagon Number: 3**

Side crack: 3 **Total damage count: 3**



**Wagon Number: 4**

Cement residue: 1 Side crack: 7 **Total damage count: 8**



**Wagon Number: 5**

Cement: 2 Side crack: 3 Total: 5



**Wagon Number: 6**

Side crack: 8 Total damages: 8



**Wagon Number: 7**

Cement residue: 1 Side crack: 6 **Total damage count: 7**



**Wagon Number: 8**

Side crack: 7 Cement: 1 **Total damages: 8**



**Wagon Number: 9**

Cement residue: 3 Side crack: 5 **Total damage count: 8**



**Wagon Number: 10**

Cement: 1 Side crack: 5 Total: 6





**Wagon Number: 11**

Side crack: 7 Cement residue: 1 **Total damage count: 8**



**Wagon Number: 12**

Cement residue: 3 Side crack: 3 **Total damage count: 6**



**Wagon Number: 13**

Side crack: 8 Cement residue: 1 **Total damage count: 9**



**Wagon Number: 14**

Cement residue: 1 Side crack: 4 **Total damage count: 5**





**Wagon Number: 15**

Cement residue: 3 Side crack: 3 Total count of all damages: 6



**Wagon Number: 16**

Side crack: 8 Cement: 2 Total: 10