


Report Generated on: February 01, 2025

Wagon Damage Report - JK Lakshmi Cement

- This report highlights damages detected in railway wagons during inspection before loading at JK Lakshmi Cement.
- Each wagon has been analyzed for cracks, rust, dents, and structural wear, ensuring transportation safety and efficiency.
 - The findings provide insights for necessary maintenance and operational improvements.

"Maintaining wagon integrity is crucial for seamless cement transportation. This report offers a clear evaluation of detected issues, ensuring proactive maintenance and uninterrupted logistics."



Wagon Damage Summary: Cement residue: 3 Side crack: 6 **Total** damage count: 9



Wagon Number: 2


Wagon Damage Summary: Cement residue: 3 Side crack: 5 **Total**

damage count: 8



Wagon Number: 3

Wagon Damage Summary: Cement residue: 1 Side crack: 5 Total



Wagon Damage Summary: Cement residue: 1 Side crack: 5 **Total**

damage count: 6


Wagon Number: 4

Wagon Damage Summary: Cement residue: 1 Side crack: 7 Total

damage count: 8

Wagon Number: 5

Wagon Damage Summary: Cement residue: 3 Side crack: 3 Total



Wagon Damage Summary: Cement residue: 3 Side crack: 3 ${f Total}$

damage count: 6

Wagon Number: 6

Wagon Damage Summary: Cement residue: 1 Side crack: 8 Total

damage count: 9

Wagon Number: 7

Wagon Damage Summary: Cement residue: 1 Side crack: 4 Total



Wagon Damage Summary: Cement residue: 1 Side crack: 4 Total

damage count: 5


Wagon Number: 8

Wagon Damage Summary: Cement residue: 3 Side crack: 3 Total

damage count: 6

Wagon Number: 9

Wagon Damage Summary: Cement residue: 2 Side crack: 8 Total



Wagon Damage Summary: Cement residue: 2 Side crack: 8 Total

damage count: 10


Wagon Number: 10

Wagon Damage Summary: Cement residue: 2 Side crack: 3 Total

damage count: 5

Wagon Number: 11

Wagon Damage Summary: Cement residue: 0 Side crack: 3 Total



Wagon Damage Summary: Cement residue: 0 Side crack: 3 Total

damage count: 3


Wagon Number: 12

Wagon Damage Summary: Cement residue: 1 Side crack:7 Total

damage count: 8

Wagon Number: 13

Wagon Damage Summary: Cement residue: 2 Side crack:3 Total



Wagon Damage Summary: Cement residue: 2 Side crack:3 Total

damage count: 5

Wagon Number: 14

Wagon Damage Summary: Cement residue: 0 Side crack:8 Total

damage count: 8

Wagon Number: 15

Wagon Damage Summary: Cement residue: 1 Side crack:5 Total



Wagon Damage Summary: Cement residue: 1 Side crack:5 **Total**