

Repair Order

Order ID: 9

Date: February 6, 2026

Client Name: Client Sample Account

Client Email: client@email.com

Technician: Technician Sample Account

Technician Email: technician@gmail.com

Device: Samsung Galaxy a06

Device Type: Smartphone

Serial Number: N9P0BN093478107

Completion Date: February 7, 2026

Identified Issues

Issue Description
Broken LCD


Price Breakdown

Item	Price (₱)
LCD Screen Replacement	1,700.00
Total Estimated Cost	₱1,700.00

Client Confirmation

Confirmation Date: February 6, 2026

Client Signature:

A handwritten signature in black ink, consisting of a stylized 'S' or 'Z' shape with a horizontal line extending to the right.

Thank you for choosing our service. We look forward to providing you with the best repair experience!