Anfa Aero Services: work order WO-2024-0036

Field	Value
Date completed	22 January 2024
Registration	CN-TFG
Aircraft	Cessna 172N
Serial number	17272851
Airframe total time at completion (h)	13,523.9
Station	Beni Mellal

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.
2. Changed engine oil and filter per the Technify maintenance manual. Gearbox oil level checked.
3. Discrepancy: Right main tire worn to the wear limit. Corrective action: Replaced right main tire.
4. Discrepancy: Left main tire worn to the wear limit. Corrective action: Replaced left main tire.
5. Discrepancy: Nose strut extension low. Corrective action: Serviced nose strut with hydraulic fluid and air.
6. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
6.00-6-6PLY	Main wheel tire	1	
6.00-6-6PLY	Main wheel tire	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: N. Berrada

Return to service: R. El Fassi, licence MA-B1-0618