# Anfa Aero Services: work order WO-2026-0172

| Field | Value |
|---|---|
| Date completed | 6 May 2026 |
| Registration | CN-TFC |
| Aircraft | Cessna 172S |
| Serial number | 172S11290 |
| Airframe total time at completion (h) | 5,878.4 |
| Station | Beni Mellal |

## *Request*

100-hour inspection.

## *Work performed*

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.
2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 78/80, 74/80, 71/80, 73/80.
3. Discrepancy: Right main tire worn to the wear limit. Corrective action: Replaced right main tire.
4. Discrepancy: Left main tire worn to the wear limit. Corrective action: Replaced left main tire.
5. Aircraft found airworthy after correction of the discrepancies listed.

## *Parts used*

| Part number | Description | Quantity | Serial number |
|---|---|---|---|
| CH48110-1 | Oil filter | 1 | |
| 6.00-6-6PLY | Main wheel tire | 1 | |
| 6.00-6-6PLY | Main wheel tire | 1 | |

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: H. Ouazzani

Return to service: K. Bennani, licence MA-B1-0212