



पश्चिम रेलवे
Western Railway

SABARMATI LOCO SHED
MECHANICAL
IC SCHEDULE FORM WAG-9HC
UNDER FRAME SECTION

Loco No.: 32456 Arr. Date: 25-09-2024 Dep. Date: 26-09-2024
Name of Supervisor: Sh. Ketan R. Vaghelasse Shift: 8117 hr. Name of Mechanic: Sh. Ramnambhai - mcf

Sr. No	DESCRIPTION (CBC schedule as per G-76)	CBC-1	CBC-2	Checked by
1	CBC No. (Make & Yr)	RIL 12-18	RIL 11-18	
2	Check for any crack by MPT test of CBC Assly Items	Checked OK	Checked OK	
	CBC coupler body	Checked OK	Checked OK	
	Knuckle	Checked OK	Checked OK	
	Knuckle Pin (Dia new-41.28 mm, cond-38.00 mm)	40.75	40.70	
	Clevis	Checked OK	Checked OK	
	Clevis Pin (Dia new-38.00 mm, cond-36.00 mm)	37.75	37.70	
Coupler Head				
3	Check tell-tail of the coupler head after coupling	Checked OK	Checked OK	
4	Check cotter pin is installed.	Checked OK	Checked OK	
5	Visual check for external damage, condition of wear plate on shank. (Std-6.00 mm & Cond-1.00 mm)	4.75	4.50	
6	Check gap between coupler head and knuckle with condemning limit gauge. If wear out is not acceptable replace knuckle etc., as advised in the maintenance manual.	Checked OK	Checked OK	
		Checked OK	Checked OK	
7	Check by inspector contour gauge (knuckle profile gauge, go gauge). Gauge no-2	Checked OK	Checked OK	Pinned Vined
8	Check wear & stretch of knuckle by using knuckle nose wear & stretch limit gauge Gauge no-3	Checked OK	Checked OK	
9	Check distortion of the coupler head by using aligning wing limit gauge	Checked OK	Checked OK	
10	Checking wear & distortion of coupler head using vertical height aligning wing pocket & guard arm gauge (no-go gauge) Gauge no-1	Checked OK	Checked OK	
11	Checking vertical height alignment & guard arm of coupler in new condition using vertical height alignment wing pocket & guard arm gauge (go gauge) Gauge no-1	Checked OK	Checked OK	
		Checked OK	Checked OK	
12	Check working of CBC & Anti creep test	Checked OK	Checked OK	
13	Check condition & proper working of CBC operating handle	Checked OK	Checked OK	
14	Check for any crack and damage in Yoke & draft gear	Checked OK	Checked OK	
Supporting device				
15	Visual check for external damage.	Checked OK	Checked OK	
16	Tighten the M16 nut & check height 165.0±1 mm both sides near the bolts.	Checked	Checked OK	
		Checked OK	Checked OK	
17	Check free lateral movement of CBC shank.	Checked OK	Checked OK	
18	Striker wear plate (new-8.00mm & Cond-2.00 mm)	7.20	7.25	
19	CBC height (std-1105 mm & Min-1030 mm)	1085 mm	1080 mm	

Check sheet for Transition screw coupling (MPMI No.25 Rev.00 RDSO Drg.No.SKDL-2894.)

Sr. No	DESCRIPTION	TSC-1	TSC-2	Checked by
1	screw coupling Make & Sr. No.	LBIC 10-23	LB 06-18	Vinod
2	Check for any crackness by DPT/MPT test	Checked OK	by lab	Nitin
3	Checking for any damage of thread & operating handle	Checked OK	Checked OK	Vinod

4	Checking of long & short shackle by Go-No go gauge (long Shackle New-43.0mm cond-39.5mm Short shackle New-28.0mm Cond-25.0mm)	42.80 27.70	42.75 27.75	
5	Check for any damage of thread & operating handle of screw coupling	Checked OK	Checked OK	Vinod
6	Check the full operation of screw coupling	Ser Fitted	Checked OK	
7	Check condition of lock washer	Checked OK	Checked OK	

UST

Sr. No	Axle Box Examination		Checked by
1	Remove earth cable.	Remove	
	Axle box No.-1 Axle box No.-7	Axle box No.-6 Axle box No.-12	
2	Axle Box cover to remove. Remove lock ring. Clean grease from surface. Check any damaged/abnormality	CE-Vinod Removed Clean Checked OK	HE- Amrish
3	UST to check by Lab personel.	CE & HE by - PPS Dak-26-09-2024	
		1 2 3 4 5 6 7 8 9 10 11 12	
	Axle no.	0412 0273 0274 05050 0588 0156	
	Brg. Make	- - - - -	
3(A)	Axle box old grease to remove fresh grease to fill, old grease sample to lab test for metal content.	Shell Gadus SSV42 Greasing done	Grease Sample Nitin
3(B)	'O' ring to change	Changed	
3(C)	Axle box cover bolts M-16x45 to torque on 100 NM.	Torque done	
	• Clamping plate bolts M-20x50 to torque on 330 NM	Torque done	Vinod
	• Inspection cover bolts M-12x35 to torqued on 85 NM	Torque done	Vinod
	• Erathing plate screw M-10x30 to torqued on 47 NM	Torque done	Amrish
4	Axle box greasing to do (as per SMI 246/TC 129 during UST)	Greasing done	Amrish
5	Insure all bolts of axle box back cover are tightened.	High done	
6	Temp. 25°C above ambient while in HHP Amb. +56°C	Checked OK	
7	Greasing for axle box every 2.5 lakh KM or 18 month of service (As per TC-0034 Shell Gadus SSV 42 p 2.5 to be use.)	Checked OK	
8	MSU greasing Clean Grease nipple. Remove grease nipple NDE Side Greasing to do. (Servoplex- SHC120 as per SMI 307 Point no A(vii)) Fit Grease nipple.	Clean Remove NDE Side Greasing done Servoplex SHC-120 Nipple tight done	Vinod
9	Wheel distance to measure:-		
	Wheel No.	1 2 3 4 5 6	Checked by
	Wheel Dist.	1596.30 1595.85 1596.00 1595.60 1596.10 1595.65	Ramankhadi

Any abnormality noticed during sch. and action taken

— Nil —



Sign of JE/SSE


Vinod & Amrish & Ramankhadi
Sign of Tech