PHASE I ENVIRONMENTAL SITE ASSESSMENT

Fairmont Assisted Living | Las Vegas, NV

Site	Fairmont Assisted Living
Address	7514 University Parkway, Las Vegas, NV 43497
Prepared For	Keel & Compass Properties
Report Date	October 11, 2023
Standard	ASTM E1527-21

Site Description

Access to the site is provided by 22 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 31.31 acres and is generally level with frontage along University Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

Access to the site is provided by 32 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 15.15 acres and is generally level with frontage along University Parkway.

Site Reconnaissance

A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. A former dry cleaner located 7 blocks to the north is listed as a closed case and is not expected to impact the site.

Vapor encroachment screening did not identify a condition requiring further evaluation. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Historical sources indicate the site was previously used for agricultural and light commercial purposes.

Site Description

Access to the site is provided by 24 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Access to the site is provided by 38 curb cuts and the property is served by municipal water and sanitary sewer. The site contains approximately 32.32 acres and is generally level with frontage along University Parkway. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Findings and Opinions

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Access and Utilities

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Access to the site is provided by 26 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Access to the site is provided by 7 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 46.46 acres and is generally level with frontage along University Parkway. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Records Review

Vapor encroachment screening did not identify a condition requiring further evaluation. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 3 blocks to the north is listed as a closed case and is not expected to impact the site. No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Historical sources indicate the site was previously used for agricultural and light commercial purposes. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site. Vapor encroachment screening did not identify a condition requiring further evaluation. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No recognized environmental conditions (RECs) were identified in connection with the subject property. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Access and Utilities

Access to the site is provided by 38 curb cuts and the property is served by municipal water and sanitary sewer. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

The site contains approximately 10.10 acres and is generally level with frontage along University Parkway. Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Access to the site is provided by 19 curb cuts and the property is served by municipal water and sanitary sewer. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

Records Review

Vapor encroachment screening did not identify a condition requiring further evaluation. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials.

Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. Vapor encroachment screening did not identify a condition requiring further evaluation. A former dry cleaner located 2 blocks to the north is listed as a closed case and is not expected to impact the site.

Site Description

The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Access to the site is provided by 9 curb cuts and the property is served by municipal water and sanitary sewer. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Regulatory Database Search Results

Database	Search Radius (mi)	Sites Within Radius	Subject Property?	Further Evaluation
NPL (Superfund)	1.0	0	No	Reviewed - no action
CERCLIS / SEMS	0.5	1	No	None
RCRA - Generators	0.5	0	No	None
RCRA - TSD	1.0	0	No	None
LUST	0.25	0	No	None
UST	0.25	0	No	None
State Hazardous Waste Sites	0.25	2	No	None
Brownfields	1.0	0	No	Reviewed - no action
Engineering Controls	1.0	0	No	Reviewed - no action
Institutional Controls	1.0	7	No	None
ERNS	0.5	2	No	None
Drycleaner Facilities	0.5	0	No	None
Solid Waste Landfills	1.0	0	No	Reviewed - no action
Voluntary Cleanup	0.5	2	No	None
Historical Auto Stations	0.25	0	No	None
NPL (Superfund)	0.25	7	No	None
CERCLIS / SEMS	0.25	7	No	Reviewed - no action
RCRA - Generators	1.0	0	No	None
RCRA - TSD	0.5	2	No	None
LUST	1.0	0	No	Reviewed - no action
UST	0.25	0	No	None
State Hazardous Waste Sites	0.25	7	No	None
Brownfields	0.5	4	No	None
Engineering Controls	1.0	0	No	None
Institutional Controls	0.25	0	No	Reviewed - no action
ERNS	0.25	0	No	None
Drycleaner Facilities	1.0	0	No	Reviewed - no action
Solid Waste Landfills	1.0	2	No	None
Voluntary Cleanup	0.25	0	No	None
Historical Auto Stations	1.0	2	No	None

Report generated 10/11/2023. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Fairmont Assisted Living and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on October 3, 2023.

_____

Grace Harper, MAI

Ridgeway Geo-Environmental

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only