PHASE I ENVIRONMENTAL SITE ASSESSMENT

Ridgeline Ironwood Student Living | Cincinnati, OH

Site	Ridgeline Ironwood Student Living
Address	5000 Market Court, Cincinnati, OH 72833
Prepared For	Whitfield Park Capital
Report Date	November 24, 2020
Standard	ASTM E1527-21

Access and Utilities

Surrounding land uses include residential, commercial and light industrial properties of similar vintage. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 27.27 acres and is generally level with frontage along Market Court. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Utilities, including electric, natural gas and telecommunications, are available to the site from the street.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site contains approximately 43.43 acres and is generally level with frontage along Market Court. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Access to the site is provided by 40 curb cuts and the property is served by municipal water and sanitary sewer.

Historical Use

No recognized environmental conditions (RECs) were identified in connection with the subject property. Vapor encroachment screening did not identify a condition requiring further evaluation. Historical sources indicate the site was previously used for agricultural and light commercial purposes. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance. A former dry cleaner located 4 blocks to the north is listed as a closed case and is not expected to impact the site.

A former dry cleaner located 6 blocks to the north is listed as a closed case and is not expected to impact the site. A review of regulatory databases identified no listings for the subject property within the ASTM-specified search distances. Vapor encroachment screening did not identify a condition requiring further evaluation. Based on the age of construction, an asbestos operations and maintenance program is recommended for suspect materials. No evidence of underground storage tanks, stained soils or stressed vegetation was observed during the site reconnaissance.

Access and Utilities

Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. The site contains approximately 28.28 acres and is generally level with frontage along Market Court. Access to the site is provided by 13 curb cuts and the property is served by municipal water and sanitary sewer. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect. Surrounding land uses include residential, commercial and light industrial properties of similar vintage.

Utilities, including electric, natural gas and telecommunications, are available to the site from the street. The site contains approximately 13.13 acres and is generally level with frontage along Market Court. Soils are typical of the region and no evidence of unsuitable conditions was observed at the time of inspection. Surrounding land uses include residential, commercial and light industrial properties of similar vintage. The site is not located within a designated 100-year floodplain according to the FEMA flood map in effect.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Certification

I certify that, to the best of my knowledge and belief, the statements of fact contained in this report are true and correct and that I have no present or prospective interest in Ridgeline Ironwood Student Living and no personal interest with respect to the parties involved.

The analyses, opinions and conclusions are limited only by the reported assumptions and limiting conditions. The inspection of the property was performed on November 7, 2020.

_____

Michael Harper, CPG

TerraSound Environmental

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only