



Seattle Department of Construction and Inspections
Elevator Section
700 Fifth Ave, Suite 2000
PO Box 34019
Seattle, WA 98124-4019

City of
SEATTLE
Elevator Inspection Report

Site No
EQP-SI-05997

Printed	Page
1/20/2022	Page 234 of 304
Inspector	
Ian Kirk	DIST 11
Total Equipment	
4	
Inspection Due	
April	

Site Address	Billing Address
ADDISON ON FOURTH 308 4TH AVE S SEATTLE 98104	ADDISON ON FOURTH PINNACLE MANAGEMENT KAREN XENOS 308 4TH AVE S SEATTLE, WA 98104

Contact Name				Contact Phone			Conveyance Service Company					
FRED BRADLEY				(206) 682-2600			Vertical Transportation Services					
City No. Owner No. City #	Status Manufacturer/Type Machine Room Location	Cap Speed	Stops # Open	Rise Cartop	K Acc P Door	P Acc Pit SS 2022	Phase I/II Key Type	Signal Main/Alt	Var	Safety Insp Date/Intvl	Accepted Last Insp	Seismic

These conveyance objects are due to be inspected by the end of April, 2021

EQP-CY-07794 1-HL 11161	Operating Without Certificate Garaventa - Garaventa Limited/Accessibility Lift (vertical included) N/A	750 17	2 2	2 No	Yes No	N/A Yes	No/No LUNAR	ADA Phone, Alarm /	No	8/6/13 5	8/6/13 12/31/20	
EQP-CY-03939 1-P 2835	Operating Without Certificate ELTEC/Cabled Elevator roof	2200 150	10	No	No No	No	No/No	/	No	9/11/19 5	8/9/62 12/31/20	Seismic & Displacement Switch
EQP-CY-03940 2-P 2836	Operating Without Certificate ELTEC/Cabled Elevator roof	2200 350	11 11	No	No No	WI No	Yes/Yes	/	No	9/12/19 5	11/20/56 12/31/20	Seismic & Displacement Switch
EQP-CY-03941 3-F 2634	Operating Without Certificate ELTEC/Cabled Elevator roof	2000 200	12	No	No No	No	Yes/Yes	/	No	9/13/19 5	11/20/56 12/31/20	Seismic & Displacement Switch

Comment Type	Comment
Comments	Old Site ID: 83471
Comment	No inspection 2020
Comment	INSPECTION WAIVED - Annual Inspection was not performed in 2021 - LC

L1 (ALL CARS)

1) LY 20 NOTE: CONTRACT YOUR VENDOR FOR ALL KEY'S, ALSO
2) LY 26 (A), (J), (L), (M), (N), (O), (P), (Q), (R), (Z). LUNAR KEY
3) C48

4) H165

5) C127

6) LY11

7) P6

8) MID9

OVER →

1-HL (11161) (RED TAGGED)

9) AL50

10) C150 NOTE: REMOVE WOOD SPACER AND USE PROBER MATERIAL.

Insp Sig	<i>Lawrence</i>	N B	Date of Inspection	6-9-2022 6-7-2022 6-13-2022
-------------	-----------------	--------	-----------------------	-----------------------------------

9)

CAR #2 (2836)

11) R20 (A) NOTE: monitor Rough on Ropes.

CAR 3-F (2634) (RED TAGGED)

12) M9

13) M95 (R) NOTE: REINSTALL MACHINE BRAILLE COIL COVER.

L 13

L 15

L 26

L 30

L 47