



May 27, 2021

Everspring Inn
8201 Aurora Ave N
Seattle WA 98103

Re: Passenger Elevator #6588
At: 8201 Aurora AV N - Everspring Inn
Inspected: May 13, 2021
Site Number: E84032 (EQP-SI-06544)

Our inspection indicates the following corrections must be made for the elevator/conveyance equipment at this site to meet current safety standards. [SBC, Section 3009.3]

1. The owner is responsible for the safe operation and maintenance of conveying equipment. Please respond with your intentions to comply with the requirements of this report. [SBC, 3010]
2. Provide a Maintenance Control Program (MCP).for the elevator(s) and other conveyances. The MCP must be available to elevator personnel. This document shall include but not be limited to the following: examinations, maintenance, and tests of equipment, cleaning, lubricating, and adjusting applicable components at regular scheduled intervals and repairs or replacing worn or defective components where necessary to maintain the installation. The maintenance procedures and intervals shall be based on: equipment age, condition, and accumulated wear, design and inherent quality of the equipment, usage, environmental conditions and improved technology. [ASME A17.1, 8.6.1.2] 2000 Maintenance
3. Maintenance records shall document compliance, and include records on the following activities: _____. [ASME A17.1, 8.6.1.4] Retro
 - a. description of maintenance task performed and dates.
 - b. description and dates of examinations, tests, adjustments, repairs, and replacements.
 - c. description and dates of call backs (trouble calls) or reports that are reported to elevator personnel by any means, including corrective action taken.
 - d. written record of the findings on quarterly testing of the firefighters' service operation.
 - e. the maintenance records shall be available to the elevator personnel.
 - f. annual test log requirements.
4. Test the Firefighters' Emergency Phase I and Phase II operation quarterly and document the dates on test log posted in the elevator machine room(s). The last recorded test date was _____. [WAC 296-96-23610] Retro
5. Clean the elevator hoistway and all related equipment. [ASME A17.1, 8.6.4.7.1] 1955 Maintenance
6. Clean the elevator car top. [ASME A17.1, 8.6.4.9] Maintenance

7. Replace the missing box covers on the car top. [NEC, 314] 1952
8. Replace the missing door operator cover on the elevator car top. [NEC, Article 620.4] 1952
9. Clean and remove combustible materials from the elevator pit. Maintain a clean pit. [ASME A17.1, 8.6.4.7] 1955 Maintenance
10. Make the elevator pit light operable. [SBC, 3011.11] Retro
11. The following keys for access to and for the operation of elevating equipment shall be tagged, labeled, and retained in the lobby key box _____. [SBC, 3011.4] Retro
 - a. **Phase I & II fire emergency service (one key for each switch) 2 more keys**
 - b. **mechanical hoistway access devices (broken arm, lunar, etc.)**
 - c. **independent, hospital emergency and or attendant operations**
 - d. **in-car stop switch**

12. Maintenance:

- Door closing force test.
- Low oil test

Your next steps:

- Contact your conveyance service company and provide them with a copy of this report;
- Schedule and complete the work.

Please complete all corrections and notify the Elevator Section at DPD of completion by letter, within 90 days of receipt of correction letter. See address below. [SBC, Section 3009]

HOW TO CONTACT THE ELEVATOR SECTION: You must either mail your completed report back to the Elevator Inspector at: City of Seattle, SDCI, **Attn: Claude Williams**, Elevator Section, PO Box 34019, Seattle, WA 98124-4019. Or fax your completed report back to the Elevator Section at SDCI at (206) 615-0540 or email.

Claude.Williams@seattle.gov

Sincerely,

Claude Williams
Elevator Inspector
206-348-3286 (cell)

CW:lc E84032 (EQP-SI-06544)