Vehicle Condition Report

en de

POWERED BY PAVE

2019 PEUGEOT BOXER

VIN # **VF3YFANF*2***9596**

INSPECTION DATE:
March 17, 2026 @ 11:06 UTC

3
FAIR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
0	3	7
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
0	4	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (2)

LEFT SIDE

Grade Score 1 Grade Score 4

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Right Rocker Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Rear Bumper Cover		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	3

WINDSHIELD

No damage