Vehicle Condition Report

en de

POWERED BY PAVE

2019 PEUGEOT BOXER

VIN # **VF3YFANF*2***9023**

INSPECTION DATE:
March 05, 2026 @ 11:54 UTC

4
GOOD

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
0	0	6
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
0	6	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (2)

LEFT SIDE

Grade Score 1 Grade Score 4

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Rear Right Door		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	3
2 Rear Right Quarter Side Molding		Missing	Part is missing	Replace	3

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage