Vehicle Condition Report

en de

POWERED BY PAVE

2023 Rivian Delivery

VIN # 7FCEFEB5*N***0100

INSPECTION DATE:
March 17, 2026 @ 06:45 UTC

3
FAIR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
1	0	13
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
8	4	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (9)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Left Center Panel		Has Severe Dent - Through Paint	> 500mm	Replace	4
2 Left Center Panel		Has Severe Dent - Not Through Paint	> 500mm	Replace	Included
3 Left Center Panel		Has Severe Dent - Not Through Paint	> 500mm	Replace	Included
6 Left Center Panel		Has Major Scrape	Scrape that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included
4 Left Quarter Panel		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	4
5 Left Quarter Panel		Has Major Scratch - Through Paint	Scratch that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
8 Right Quarter Panel		Has Severe Dent - Through Paint	> 500mm	Replace	4
9 Right Quarter Panel		Has Major Scrape	Scrape that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included

FRONT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
7 Front Left Mud Flap		Missing	Part is missing	Replace	1

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage