Vehicle Condition Report

en de

POWERED BY PAVE

2023 Rivian Delivery

VIN # 7FCEFEB5*N***0240

INSPECTION DATE:
March 04, 2026 @ 07:09 UTC

3
FAIR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
0	0	7
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
4	3	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (8)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Left Roof Line		Has Major Dent - Through Paint	230mm to 255mm	Replace	4
1 Left Roof Line		Has Severe Dent - Through Paint	> 500mm	Replace	Included
3 Left Roof Line		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	Included
4 Left Roof Line		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	Included
5 Left Roof Line		Has Severe Dent - Not Through Paint	> 500mm	Replace	Included
6 Left Roof Line		Has Severe Dent - Not Through Paint	> 500mm	Replace	Included

7 Left Roof Line		Has Major Scratch - Through Paint	Scratch that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
8 Rear Right Quarter Side Molding		Has Major Dent - Through Paint	230mm to 255mm	Replace	3

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage