Vehicle Condition Report

en de

POWERED BY PAVE

2019 PEUGEOT BOXER

VIN # **VF3YFANF*2***5624**

INSPECTION DATE:
March 20, 2026 @ 09:16 UTC

4
GOOD

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
0	0	6
Left Side: TOTAL GRADE SCORE	**Right Side:** TOTAL GRADE SCORE	
3	3	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (2)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Front Left Window Trim		Missing	Part is missing	Replace	3

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Rear Right Quarter Side Molding		Missing	Part is missing	Replace	3

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage