Vehicle Condition Report

en de

POWERED BY PAVE

2019 PEUGEOT BOXER

VIN # **VF3YFANF*2***4204**

INSPECTION DATE:
March 20, 2026 @ 09:26 UTC

2
POOR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
1	0	22
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
0	21	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (12)

LEFT SIDE

Grade Score 1 Grade Score 4

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
5 Right Quarter Panel		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	4
3 Right Quarter Panel		Has Severe Dent - Through Paint	> 500mm	Replace	Included
4 Right Quarter Panel		Has Major Scratch - Through Paint	Scratch that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included

6 Right Quarter Panel		Has Severe Dent - Not Through Paint	> 500mm	Replace	Included
7 Right Rocker Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
12 Right Roof Line		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
10 Front Right Door Body Side Molding		Missing	Part is missing	Replace	3
2 Rear Right Door		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	3
8 Rear Right Door		Has Severe Dent - Not Through Paint	> 500mm	Replace	Included
9 Rear Right Door		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	Included
11 Rear Right Quarter Side Molding		Missing	Part is missing	Replace	3

FRONT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Front Tow Hook		Missing	Part is missing	Replace	1

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage