Vehicle Condition Report

en de

POWERED BY PAVE

2021 MERCEDES 314 CDI SPRINTER

VIN # **W1V91063*P***0877

INSPECTION DATE:
March 19, 2026 @ 11:02 UTC

3
FAIR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE
0	0
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**
4	7

Total Grade Score All Damages:
11

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (4)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Left Roof Line		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Right Rocker Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4

3 Rear Right Door		Has Severe Dent - Through Paint	> 500mm	Replace	3
4 Rear Right Door		Has Major Scrape	Scrape that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage