# Vehicle Condition Report

en de

POWERED BY PAVE

## 2023 Rivian Delivery

VIN # 7FCEFEB5*N***0056

INSPECTION DATE:
March 04, 2026 @ 06:56 UTC

4
GOOD

| Front Side: TOTAL GRADE SCORE | Back Side: TOTAL GRADE SCORE | Total Grade Score All Damages: |
|---|---|---|
| 0 | 0 | 3 |
| **Left Side: TOTAL GRADE SCORE** | **Right Side: TOTAL GRADE SCORE** | |
| 0 | 3 | |

## Vehicle Photos

ORIGINAL INSPECTION

## Upload Photos

OPTIONAL

No photo

## Exterior (1)

LEFT SIDE

Grade Score 1 Grade Score 4

RIGHT SIDE

Grade Score 1 Grade Score 4

### Damages Details

| COMPONENT | CROPPED PHOTO | DAMAGE TYPE | SEVERITY | REPAIR METHOD | GRADE SCORE |
|---|---|---|---|---|---|
| 2 Front Right Door Body Side Molding | | Missing | Part is missing | Replace | 3 |

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage