Vehicle Condition Report

en de

POWERED BY PAVE

2024 MERCEDES 315CDI L2 DIESEL RWD

VIN # **W1V3HBFZ*P***4588**

INSPECTION DATE:
March 04, 2026 @ 09:16 UTC

3
FAIR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
0	2	13
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
7	4	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (6)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Left Center Panel		Has Major Dent - Not Through Paint	230mm to 255mm	Replace	4
1 Front Bumper Cover		Has Medium Crack	130mm to 150mm	Replace	3

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE

3 Right Quarter Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
4 Right Quarter Panel		Has Major Scratch - Through Paint	Scratch that is 300mm or longer or more than 70mm wide	Repair & Refinish	Included
5 Right Quarter Panel		Has Major Dent - Through Paint	230mm to 255mm	Replace	Included

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
6 Rear Step		Has Medium Crack	130mm to 150mm	Replace	2

WINDSHIELD

No damage