# Vehicle Condition Report

en de

POWERED BY PAVE

## 2021 Ford Transit

VIN # **WF0EXXTT*M***8528**

INSPECTION DATE:
March 17, 2026 @ 06:35 UTC

3
FAIR

| Front Side: TOTAL GRADE SCORE | Back Side: TOTAL GRADE SCORE | Total Grade Score All Damages: |
|---|---|---|
| 0 | 0 | 7 |
| **Left Side: TOTAL GRADE SCORE** | **Right Side: TOTAL GRADE SCORE** | |
| 3 | 4 | |

## Vehicle Photos

ORIGINAL INSPECTION

## Upload Photos

OPTIONAL

No photo

## Exterior (6)

LEFT SIDE

Grade Score 1 Grade Score 4

### Damages Details

| COMPONENT | CROPPED PHOTO | DAMAGE TYPE | SEVERITY | REPAIR METHOD | GRADE SCORE |
|---|---|---|---|---|---|
| 1 Rear Left Quarter Side Molding | | Has Major Dent - Not Through Paint | 230mm to 255mm | Replace | 3 |

RIGHT SIDE

Grade Score 1 Grade Score 4

### Damages Details

| COMPONENT | CROPPED PHOTO | DAMAGE TYPE | SEVERITY | REPAIR METHOD | GRADE SCORE |
|---|---|---|---|---|---|
| 3 Right Roof Line | | Has Major Dent on Seam Line - Not Through Paint | Major dent 230mm to 255mm but on seam line | Replace | 4 |

| | | | | | |
|---|---|---|---|---|---|
| 2 Right Roof Line |  | Has Major Scrape | Scrape that is 300mm or longer or more than 70mm wide | Repair & Refinish | Included |
| 4 Right Roof Line | | Has Major Dent on Seam Line - Not Through Paint | Major dent 230mm to 255mm but on seam line | Replace | Included |
| 5 Right Roof Line | | Has Major Dent - Not Through Paint | 230mm to 255mm | Replace | Included |
| 6 Right Roof Line | | Has Major Dent - Through Paint | 230mm to 255mm | Replace | Included |

FRONT SIDE

Grade Score 1 Grade Score 4

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage