Vehicle Condition Report

en de

POWERED BY PAVE

2023 Rivian Delivery

VIN # 7FCEFEB5*N***0281

INSPECTION DATE:
March 17, 2026 @ 06:48 UTC

3
FAIR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
1	0	11
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
0	10	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (4)

LEFT SIDE

Grade Score 1 Grade Score 4

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Right Quarter Panel		Has Severe Dent - Not Through Paint	> 500mm	Replace	4
4 Front Right Door Body Side Molding		Missing	Part is missing	Replace	3
3 Rear Right Quarter Side Molding		Has Medium Hole	130mm to 150mm	Replace	3

FRONT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Front Left Mud Flap		Missing	Part is missing	Replace	1

BACK SIDE

Grade Score 1 Grade Score 4

WINDSHIELD

No damage