Vehicle Condition Report

en de

POWERED BY PAVE

2019 PEUGEOT BOXER

VIN # **VF3YFANF*2***5290**

INSPECTION DATE:
March 20, 2026 @ 09:03 UTC

2
POOR

Front Side: TOTAL GRADE SCORE	Back Side: TOTAL GRADE SCORE	Total Grade Score All Damages:
1	3	22
Left Side: TOTAL GRADE SCORE	**Right Side: TOTAL GRADE SCORE**	
4	14	

Vehicle Photos

ORIGINAL INSPECTION

Upload Photos

OPTIONAL

No photo

Exterior (8)

LEFT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
1 Left Quarter Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4

RIGHT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
3 Right C-Pillar		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4

5 Right Rocker Panel		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	4
4 Front Right Door Body Side Molding		Missing	Part is missing	Replace	3
6 Rear Right Quarter Side Molding		Missing	Part is missing	Replace	3

FRONT SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
2 Front Tow Hook		Missing	Part is missing	Replace	1

BACK SIDE

Grade Score 1 Grade Score 4

Damages Details

COMPONENT	CROPPED PHOTO	DAMAGE TYPE	SEVERITY	REPAIR METHOD	GRADE SCORE
8 Rear Bumper Cover		Has Large Crack	Significant crack	Replace	3
7 Right C-Pillar		Has Major Dent on Seam Line - Not Through Paint	Major dent 230mm to 255mm but on seam line	Replace	Included

WINDSHIELD

No damage