

Fleet Protect 365

End-of-Shift Inspection Report

DEMONSTRATION SAMPLE - FICTIONAL COMPANY, DRIVER, EQUIPMENT, LOCATIONS, AND PHOTOS

Driver & Report Information

Company	ABC Freight
Driver	Joe Public
Employee ID	9000001
Report ID	ABC-JP-20260821-001
Shift Date	08/21/2026
Report Emailed To	joe.public@example.com (fictional)
Inspection Count	3
Application Version	Driver Demo

Inspection 1 - 53' Trailer

Inspection ID	DEMO-INS-0001
Submitted	08/21/2026, 07:12:44 AM CDT
Truck	681204
Trailer 1	418275
Location From	1201
Location To	2408
Notes	NA

Compliance Audit Trail

Pre-Trip Checklist	Completed
Pre-Trip Completed By	Joe Public
Pre-Trip Date/Time	08/21/2026, 07:12:44 AM CDT
Inspection Submitted By	Joe Public

Inspection Submitted Date/Time	08/21/2026, 07:12:44 AM CDT
Driver Certification	Certified complete and accurate
Certified By	Joe Public
Certification Date/Time	08/21/2026, 07:12:44 AM CDT

Photo Documentation (4)

Fifth wheel plate connected

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of connection point

Landing gear raised

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of landing gear

Air, brake, and electrical lines connected

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of lines and connections

Rear door and seal secure

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of rear door and seal

Inspection 2 - 53' Trailer

Inspection ID	DEMO-INS-0002
Submitted	08/21/2026, 01:38:09 PM CDT
Truck	681204
Trailer 1	509316
Location From	2408
Location To	7310
Notes	Equipment secure; no defects observed.

Compliance Audit Trail

Pre-Trip Checklist	Completed
Pre-Trip Completed By	Joe Public
Pre-Trip Date/Time	08/21/2026, 01:38:09 PM CDT
Inspection Submitted By	Joe Public
Inspection Submitted Date/Time	08/21/2026, 01:38:09 PM CDT
Driver Certification	Certified complete and accurate
Certified By	Joe Public
Certification Date/Time	08/21/2026, 01:38:09 PM CDT

Photo Documentation (4)

Fifth wheel plate connected

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of connection point

Landing gear raised

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of landing gear

**Air, brake, and electrical lines
connected**

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of lines and connections

Rear door and seal secure

SAMPLE TRAINING PHOTO

CAMERA IMAGE PLACEHOLDER

Sample view of rear door and seal

AMPLE - NOT A REAL REPORT

Inspection 3 - Bobtail

Inspection ID	DEMO-INS-0003
Submitted	08/21/2026, 05:46:31 PM CDT
Truck	681204
Location From	7310
Location To	1201
Notes	Returned bobtail to the ABC Freight terminal.

Compliance Audit Trail

Pre-Trip Checklist	Completed
Pre-Trip Completed By	Joe Public
Pre-Trip Date/Time	08/21/2026, 05:46:31 PM CDT
Inspection Submitted By	Joe Public
Inspection Submitted Date/Time	08/21/2026, 05:46:31 PM CDT
Driver Certification	Certified complete and accurate
Certified By	Joe Public
Certification Date/Time	08/21/2026, 05:46:31 PM CDT

Photo Documentation (0)

Photos	No photos required for this Bobtail inspection.
--------	---

End-of-Shift Completion

End-of-Shift Checklist	Completed
Completed By	Joe Public
Employee ID	9000001
Completion Date/Time	08/21/2026, 06:02:18 PM CDT

Driver Certification

Certification Statement	I certify that this inspection report and all submitted photographs are true and accurate to the best of my knowledge.
Certified By	Joe Public
Employee ID	9000001
Certification Date/Time	08/21/2026, 06:02:18 PM CDT

This document is a fictional demonstration sample. It is not an operational inspection record and must not be used for compliance, employment, insurance, or legal purposes.