

Emma's Construction Site

2022-08-11 to 2022-08-18

Site Metrics

Exclusion Zone Detection

22

Detected Breaches

23

Close Proximity Warnings

70

Percent Compliant

Loose Object Detection


128

Loose Objects Detected


24

Objects Remaining

Average Incidents by Hour



Incidents by Camera



Incidents by Date

