


Toyota Avensis


VIN: **SB1EG76L20E090805**


Gasoline

Generated on **2023-08-07 15:56**





Theft







Odometer






Financial and legal status






Damage




Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?





We didn't find any records that the vehicle was stolen.

Here's what we checked:




Currently wanted as stolen


 No record found




Stolen in the past

 No record found

Current status unknown



Stolen in the past

 No record found

Vehicle has been recovered

Police database stolen vehicle **check completed in:**

 Slovakia

 Italy

 Sweden

 Slovenia

 Czechia


 Finland


 Canada


 Romania

Odometer

Are there signs of mileage rollbacks or discrepancies?

 Last known mileage: 107,068 km

 12 mileage records found



Odometer records

2013-07	11 km
2014-06	16,189 km
2015-11	31,600 km
2016-09	46,710 km
2018-08	69,700 km
2019-05	79,556 km

Odometer records

2020-09	89,405 km
2020-09	89,521 km
2022-07	100,051 km
2023-02	104,806 km
2023-06	107,020 km
2023-07	107,068 km

Financial and legal status

Has the vehicle passed its technical inspections? Does it have property rights restrictions or outstanding loans?



Tech inspection is valid

Legal



Technical inspection (also known as MOT)

Passed 2023-02

 **Poland**

Has successfully passed
technical inspection



Scrap

✓ No record found

No record that vehicle was
marked as scrapped



Exported

✓ No record found

No export records found



Imported

✓ No record found

No import records found

Financial restrictions



Lease

✓ No record found

No data available on outstanding loan or finance agreement



Operating-lease

✓ No record found

No record of vehicle being on an operating-lease



Unit-stocking

✓ No record found

No record of vehicle being under unit-stocking finance

Damage

Has this vehicle been damaged in the past? What was the value of the damages?



This vehicle was damaged 2 times!



Mild damages normally won't impact a vehicle's safety or leave structural issues

Damage records



Rear right / Bumper

Damage

2019-04

Estimated Repair Cost

€1,000

Possible Damage Cause


Unknown

Damage Groups

Exterior body parts

External lightning

Structural elements of the body



Damage

2022-04

Estimated Repair Cost

€5,000

Possible Damage Cause

Unknown


Damage Groups

Exterior body parts

Glass

Specs & equipment

What specs and equipment are on record for this vehicle?

 Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications



Make
Toyota



Model
Avensis



Body type
Estate



Powertrain
displacement
1.8 L



Powertrain power
108 kW (145 hp)



Fuel type
Gasoline



Transmission type
Automatic



Engine description
**1.8L PETROL
VALVEMATIC**



Number of seats
5



Engine code
2ZR-FAE

Equipment

HEATER

EMERGENCY BRAKE LIGHTS

STANDARD

ROUGH ROAD PACKAGE

WITHOUT

PACKAGE OPTION 2

WITHOUT

VSC

VSC+ (W/ CUT OFF SWITCH)

AUDIO

AM/FM CD BT 6SP

GRADE PACKAGE

SOL PACK (MID GRADE)

TIRE & DISC WHEEL AVENSIS

OTHER SPEC (010) USED

A/C

AUTO

JACK

WITH

SEAT HEATER

WITHOUT

HEADLAMPS

STANDARD + DRL

CRUISE CONTROL

WITH

SHIFT LEVER & KNOB

LEATHER (6MT)

SEAT LUMBER SUPPORT

2 WAY POWER (ONLY D-SIDE)

WASHER FLUID

WITH

TIRE & DISK WHEEL

205/60R16 6.5J ALLOY

EXHAUST EMISSION CONTROL

WITH

SPARE TYRE

TEMP 145/70D17

ECO PACKAGE

WITHOUT

REAR ARM REST

WITH (WITH TRUNK THROUGH)

EMV AND NAVIGATION SYSTEM

WITHOUT

LUGGAGE HOLDING BELT

ONLY HOOK (4)

DOOR SCUFF PLATE

RESIN (WITHOUT ORNAMENT)

SEAT MATERIAL

FABRIC E

HEADLAMP LEVELLING

MANUAL

FRONT HEADRESTS

2-WAY ACTIVE

REAR COMBINATION LAMP

LED (STOP/TAIL)

SEAT BACK POCKET

WITH (DRIVER + PASSENGER)

ANTI-THEFT LABEL

WITHOUT

PARKING BRAKE

E-PB (MT: W/ DAR, AT: W/O DAR)

OUTSIDE REAR VIEW MIRROR

COLOUR PWR HEAT

SIDE GLASS

GREEN

SUN SHADE

EU GAS STEP 5+ (W/E OBD)

RADIATOR GRILLE

NORMAL

REAR SPOILER

WITH

ENGINE

1NR-FE ECO (STOP&START)

WIRELESS DOOR LOCK

D+P: BACK DOOR+ANSWER BACK

LANE KEEP ASSIST (LKA)

WITHOUT

AUDIO JACK

MINI JACK+USB PORT

INTERMITTENT WIPER

RAIN SENSORS WITH

LUGGAGE ROOM & DECK TRIM

WITHOUT SIDE BOARD

STEERING WHEEL

LEATHER

WVTA GENERATION SPEC

SEG F

REAR CONSOLE BOX

WITH LID

PACKAGE OPTION 3

WITHOUT

REGULATION COMPLIANCY

EUROPE WVTA LASER LABEL +ID

TRUNK & DECK CARPET & MAT

WITHOUT LUGGAGE RAIL SYSTEM

LIGHT CONTROL SYSTEM

WITH

SPEEDOMETER

WITHOUT

COLD AREA PACKAGE

EUROPE

HEADLAMP CLEANER

WITH

PRE-CRASH SYSTEM

WITHOUT

FRONT FOG LAMPS

WITH

DAYTIME RUNNING LIGHT SYSTEM

WITH (BULB TYPE)

CLEARANCE & BACK SONAR

WITHOUT

WINDSHIELD DEICER

WITHOUT

TIRE BRAND

UNSPECIFIED

POWER WINDOWS

ALL ONE TOUCH

BACK MONITOR (REAR VIEW CAMERA)

WITHOUT

ABS

WITH

OWNER'S MANUAL

WITHOUT

INSIDE REAR VIEW MIRROR

DAY AND NIGHT, EC

STEERING COLUMN

MANUAL TILT AND TELESCOPIC

PACKAGE TRAY TRIM & TONNEAU COVER

TONNEAU COVER ONLY

SUN ROOF & MOON ROOF

Timeline

5 records found

The timeline of records for this vehicle

Records

2013-07

 Poland



Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

2019-04

 Poland



Damage detected

We have indications that this vehicle was recognised as damaged in this particular country (or state). Please refer to the “Damage” section for details.

2022-04

 Poland



Damage detected

We have indications that this vehicle was recognised as damaged in this particular country (or state). Please refer to the “Damage” section for details.

2023-02

 Poland



Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

2023-07

 Poland



Was on sale

This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.