

Mianwal Ranjha Sanitation Repairs

Source brief · Historical report summary

Source: PROGRESS REPORT 2024 Revised.docx, Repair and Cleaning of Sewerage Scheme

About the project

HRPF's 2024 progress report documents the cleaning and repair of the sewerage scheme in Mianwal Ranjha in the public interest. The work addressed damaged pipes and roadside openings as part of efforts to improve local sanitation.

The report also records a separate request to the Drain Department Punjab to increase the capacity of the Fifth Drain. That request is distinct from the completed cleaning and repair work.

The challenge

Damaged sewerage pipes and the condition of roadside openings required attention to support public health and sanitation. The report identifies repair and cleaning of the existing scheme as the immediate work undertaken.

A request for greater drainage capacity was also submitted. The report does not provide technical measurements or confirm that the capacity expansion was completed.

Our approach

The reported intervention focused on cleaning the existing scheme, repairing broken pipes and raising the level of roadside openings. A separate institutional request addressed the capacity of the Fifth Drain.

The completed repairs and the pending capacity request are presented separately so visitors can understand the reported outcome accurately.

Objectives

Support public health and sanitation in Mianwal Ranjha.

Restore damaged parts of the existing sewerage scheme.

Raise the drainage-capacity concern with the relevant department.

Activities

Cleaning of the local sewerage scheme.

Repair of broken pipes.

Raising of roadside openings.

Submission of a request to increase the Fifth Drain's capacity.

Reported outcomes

The report records completion of cleaning and repair work.

Broken pipes were repaired.

Roadside openings were raised.

The drainage-capacity request was submitted; completion of an expansion is not established.

Evidence and scope

The Drain Department Punjab is named as the recipient of the request to increase the Fifth Drain's capacity. The source does not name a formal project partner, contractor or donor.

This project page describes the work recorded in the 2024 report. Exact work dates, expenditure, pipe lengths and the number of households served are not supplied. The completed repair work should not be read as confirmation of a completed drainage expansion.

Source: PROGRESS REPORT 2024 Revised.docx, Repair and Cleaning of Sewerage Scheme. The project description is a website summary of this historical report. Timeline labels describe the sequence in the report and are not exact event dates. Gallery photos come from HRPF's supplied archive and illustrate the Foundation's wider work; they are not verified photographs of this specific intervention.