


Cedar Clinic Punch List - Floor 1



Callout	Symbol	Location	Issue	Owner	Due	Priority	Status
P1	red circle	A102 under sink	Active leak	Mei	2026-07-09	P0	Open
E2	yellow triangle	A101 west wall	GFCI outlet mislabeled	Omar	2026-07-12	P2	Blocked by permit
F3	blue square	A103 south door	Cracked floor tile	Lina	2026-07-15	P3	Done