Vehicle Tyres Inspection Report

Generated: 2026-11-12
Document No: INS-VALIDATI
Inspection Date: N/A

Vehicle Details

Asset No.	**TEST-ASSET**
Site	**N/A**
Vehicle Type	**WHEEL_LOADER**
Tyreman	**N/A**
Status / Meters	**Complete** No meter reading
Inspection Date	**N/A**

Inspection Summary

1	1	0	0	4
Checked of 5	Good	Wear	Damage	No Data

Avg Pressure
80 PSI

Photos Attached
0 of 5

Vehicle Tyre Condition Map



Position data requires review. Unmapped recorded positions: invalid_slot.

Inspection Findings

- 1 of 5 tyre positions were checked; 4 have no reading.
- No visible wear or damage recorded on any checked tyre.
- Average recorded tyre pressure: 80 PSI (1 reading).
- No photo evidence attached.
- Inspection completed and approved.

Vehicle Tyres Inspection Report

Generated: 2026-11-12
Document No: INS-VALIDATI
Inspection Date: N/A

Tyre Inspection Details

Position	Serial No.	Brand	Pressure (PSI)	Tread / Visual Condition	Status	Notes
LHF1	N/A	N/A	N/A	Not checked	No Data	-
RHF1	N/A	N/A	N/A	Not checked	No Data	-
LHR1	N/A	N/A	N/A	Not checked	No Data	-
RHR1	N/A	N/A	N/A	Not checked	No Data	-
invalid_slot	N/A	N/A	80	Good	Good	-

Inspection Notes & Compliance Checks

No.	Item	Result	Remarks
1	Tyre pressure recorded	Pass	1 of 1 checked positions, 80 PSI average
2	Pressure consistency across the vehicle	N/A	Fewer than 4 readings to compare
3	Tread and sidewall condition	Pass	No visible wear or damage recorded
4	Tread depth measured	N/A	Tread depth not measured
5	All tyre positions checked	Check	1 of 5 positions
6	Photo evidence captured	Check	No photos attached
7	Overall vehicle condition (tyres)	Pass	Satisfactory

Sign-off

Tyreman Signature

Pending

Not recorded
Inspected: N/A

Approver Signature

Pending

Not recorded
Approved: N/A

Scan to verify this report