



# Smart Ultrasonic NDT Inspection System

AI-Assisted Ultrasonic Signal Processing and Defect Detection


Select Specimen Condition

Possible Defect

▼



## Ultrasonic A-Scan



## Detected Echoes

Number of Peaks

3

Maximum Amplitude

1.05



Possible defect indication detected



## Defect Analysis

 Defect detected in specimen

The ultrasonic signal contains an additional echo.

This may indicate a possible internal defect.

 Possible defect indication detected

Defect position: 44.84 time units

Echo amplitude: 0.85