



Smart Ultrasonic NDT Inspection System

AI-Assisted Ultrasonic Signal Processing and Defect Detection


Select Specimen Condition

Normal

▼



Ultrasonic A-Scan



Detected Echoes

Number of Peaks

2

Maximum Amplitude

1.02



Defect Analysis



No significant defect detected

The ultrasonic signal shows normal echo patterns.



No significant defect indication detected