Date and Time: 2023-05-25 21:17:48

Image Name: Camera Feed

Real-Time Railway Track Fault Area Prediction

Predicted Class	Area (cm^2)
Crack Detected	44.08
Missing Bolt	5.59
Missing Bolt	6.58
Crack Detected	53.06
Missing Rail Clip	10.88
Crack Detected	5.12

Total Number of Class Counts

Missing Rail Clip	1
Missing Bolt	2
Crack Detected	3