



Motor Number: 444

Power Rating: 383 HP

Operating Condition Summary for 1 Month:



Current condition of motor: Healthy

Estimated Remaining Useful Life (RUL): 0.82

Fault Table Summary

Fault Type	Occurrence in Week		Occurrence in Month		Occurrence in Year	
	Frequency	Time	Frequency	Time	Frequency	Time
Broken Rotar-Bar (BR)	1	1	1	1	1	1
Broken End Ring	1	1	1	1	1	1
Eccentricity	1	1	1	1	1	1
Bearing	1	1	1	1	1	1
Inter-turn Short Circuit	1	1	1	1	1	1

Suggestions Based On Current Situation: Normal