

**Motor Number: 766** 

**Power Rating: 199 HP** 

## **Operating Condition Summary for 1 Month:**





**Current condition of motor: Healthy** 

Estimated Remaining Useful Life (RUL): 0.82

## **Fault Table Summary**

Fault Type	Occurrence in Week		Occurrence in Month		Occurrence in Year	
	Frequency	Time	Frequency	Time	Frequency	Time
Broken Rotar-Bar (BR)	1	1	1	1	1	1
Broken End Ring	1	1	1	1	1	1
Eccentricity	1	1	1	1	1	1
Bearing	1	1	1	1	1	1
Inter-turn Short Circuit	1	1	1	1	1	1

**Suggestions Based On Current Situation: Normal**