

## Login

Email

Password

Login



U151(영광)   U113(영광)   U120(하이퐁)

### 특이사항

[44299] PCS fault status ON 알람 관련 냉각수 플럭싱 및 PCS 리액터 교체 작업 진행 중

편집

### 기간 선택

생성 일자:

2024 ▾

12 ▾

28 ▾

미리보기 생성

U151(영광)   U113(영광)   U120(하이풍)

특이사항

[44299]PCS fault status ON알람 관련 냉각수 플럭싱 및 PCS 리액터 교체 작업 진행 중


편집

기간선택


생성일자: 2024 12 28

일별 운전 현황			
운전 기간	`24.07.02 00:00 ~ 24:00	작성일	2024년 07월 04일
평균 풍속	10.76 m/s	발전량	78,374.73 kWh (CF: 75.94%)
운전 시간 (가동률)	24h 00m (100.00%)	발전 시간	23h 30m
누적 운전 현황			
운전 기간	`19.09.03 00:00 ~ `24.07.02 24:00 (42,360h)	누적 발전량	37,791,516.04 kWh (CF: 23.58%)
누적 운전 시간	37,269h 50m (87.98%)	누적 발전 시간	23,910h 8m

출력 곡선 (`24.07 ~ `24.09)



Time chart (24/07/02)



에러 발생 현황		
발생 일시	에러코드	내용
2024-07-02 13:13	20001	Low wind speed
2024-07-02 13:20	20007	Overtime startup

1. 주요 이벤트 현황

1)특이사항 없음

2. 주요 에러 발생현황 및 조치사항

1)특이사항 없음

3. 현장이슈 발생현황

1)특이사항 없음

Generate file



## Users

새로 만들기

Id	Name	Role	Last Login	Delete	Edit
lillywilliams@gmail.com	Lilly Williams	Admin	2 days ago	Delete	Edit
emiliaclark@gmail.com	Emilia Clark	User	2 days ago	Delete	Edit
ninadobrev@gmail.com	Nina Dobrev	User	2 days ago	Delete	Edit
selenagomez@gmail.com	Selena Gomez	User	2 days ago	Delete	Edit
dakotajohnson@gmail.com	Dakota Johnson	User	4 days ago	Delete	Edit



# 새 유저

User id

userid

Password

password

Retype  
password

retype password

User name

user name

Role

role



유저 추가

Cancel