

EcoDriveAI Predictive Telemetry Report

Metric Matrix	Value Logs
Brand Layout / Production Era	Bajaj (2012)
Displacement Assembly	150 cc / Carburetor
Odometer Tracking	45,000 km
Fuel Trim Adjustments (STFT)	9.8%
Combustion Core Heat (EGT)	740 °C
Active Cylinder Misfires	3

Engine Diagnosis Analytics Target

Integrated Vehicle Health Score: 25.3/100
Risk Status Bracket: Critical Phase Separation Risk

Maintenance Mitigation Recommendations

Critical hazard alert. Lean thermal loading spikes detected. Check line materials for cracks, flash injector paths, and isolate tank condensation before continuing E20 fuel tracking.