

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-26 22:16 UTC

Report Ref No:	REP-2026-CIL-002	Inspection Date:	2026-09-22
Mine Facility:	Kusmunda Mega Opencast Mine (SECL-KUS-01)	Subsidiary:	South Eastern Coalfields Limited
Contractor Agency:	Gati Heavy Earthmovers Ltd	Inspecting Officer:	Amitabh Singh (Senior Overman / Safety Inspector)
Inspection Type:	Contractor Compliance	Geo-Coordinates:	22.3405° N, 82.6861° E
Compliance Score:	94.0 / 100	Workflow Status:	UNDER_MINE_MANAGER_REVIEW

AI-ASSISTED RISK ASSESSMENT: 11.0/100 — [LOW]

Contributing Factors: Contractor Compliance compliance posture evaluated against statutory norms.

Recorded Violations & Corrective Directives

Violation Code	Category	Severity	Statutory Reference & Details
VIO-BCCL-26-004	Safety	CRITICAL	Fire Seam Encroachment Without Nitrogen Flushing: Excavation into active pyritic fire zone without prior thermal imaging and inert gas blanketing.

FIELD OFFICER VERIFICATION Digitally Signed & Submitted Date: 2026-09-22	MINE MANAGER VALIDATION Reviewed and Enforced Action Assigned	CORPORATE GOVERNANCE (CIL) Statutory Compliance Seal Status: APPROVED
---	--	--