

GOVERNMENT OF INDIA • MINISTRY OF COAL

COAL INDIA LIMITED (CIL) • CENTRAL MINE GOVERNANCE SYSTEM

Official Statutory Inspection & Compliance Audit Report — Generated: 2026-09-28 13:50 UTC

Report Ref No:	REP-260928-12AFF6	Inspection Date:	2026-09-28
Mine Facility:	Rajmahal Open Cast Project (ECL-OCP-01)	Subsidiary:	Eastern Coalfields Limited
Contractor Agency:	Direct Operations	Inspecting Officer:	Amitabh Singh (Senior Overman / Safety Inspector)
Inspection Type:	Safety	Geo-Coordinates:	23.7957° N, 86.4304° E
Compliance Score:	90.0 / 100	Workflow Status:	APPROVED

AI-ASSISTED RISK ASSESSMENT: 45.0/100 — [LOW]

Contributing Factors: Normal operation standards met.

Statutory Checklist Findings

Item / Rule	Category	Result	Remarks
Dust suppression system	Safety	PASS	Checked
PPE compliance check	Safety	FAIL	2 workers without helmets

FIELD OFFICER VERIFICATION Digitally Signed & Submitted Date: 2026-09-28	MINE MANAGER VALIDATION Reviewed and Enforced Action Assigned	CORPORATE GOVERNANCE (CIL) Statutory Compliance Seal Status: APPROVED
--	---	---