

AutoSentinel

Premium Unauthorized Construction Detection Report

Generated: 03 August 2026, 22:21 IST | Analysis period: 2019–2026

Area analysed: Mapped construction alert

Table of contents

Table of contents	1
Zone Details	2
Bhuvan Land-use Verification	2
How the Risk Score Was Calculated	2
Satellite Evidence	2

Zone Details

Severity: CRITICAL | Risk Score: 90.2/100

Field	Value
Zone ID	655
Coordinates	19.390497°N, 72.852362°E
Constructed Area	5.18 hectares (51,800 sq metres)
Severity Level	CRITICAL
Risk Score	90.2 / 100
Violation Type	FOREST ENCROACHMENT
Bhuvan Land Classification	Forest fringe
Bhuvan Overlap / Confidence	78.4% / 88%
Bhuvan Data Source	Satellite land-use assessment
OSM Overlays	FOREST ENCROACHMENT, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW
Legal Flags	FOREST ENCROACHMENT, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW
Risk Boost	34.5

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Forest fringe**; polygon overlap: **78.4%**; confidence: **88%**. Source: Satellite land-use assessment.

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	5.18 ha	Primary driver - larger = higher score
Land Classification	FOREST ENCROACHMENT	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2026	Change detection window
Final Score	90.2/100	Severity: CRITICAL

This zone received a CRITICAL score of 90.2/100 because the detected construction covers 5.2 hectares - exceeding the 5-hectare threshold that indicates large-scale unauthorized development. Structures of this size cannot be accidental extensions and should be reviewed against local approvals.

Land Classification Note: The construction location falls within an area classified as protected forest or woodland in the available reference overlays. Construction on forest land without Forest Department clearance may be prohibited under the Forest Conservation Act, 1980.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2026 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2026 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.