

AutoSentinel

Unauthorized Construction Detection Report

Generated: 25 July 2026, 22:40 IST | Analysis period: January 2025–January 2026

Area analysed: Mapped construction alert

Severity: MEDIUM | Risk Score: 41.0/100

Zone Details

Field	Value
Zone ID	918
Coordinates	19.351724°N, 72.832618°E
Constructed Area	0.22 hectares (2,200 sq metres)
Severity Level	MEDIUM
Risk Score	41.0 / 100
Violation Type	UNVERIFIED ZONE
Bhuvan Land Classification	Mixed-use development
Bhuvan Overlap / Confidence	80.4% / 90%
Bhuvan Data Source	ISRO Bhuvan LULC mock verification
OSM Overlays	PROTECTED LAND, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW
Legal Flags	PROTECTED LAND, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW
Risk Boost	18.5

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Mixed-use development**; polygon overlap: **80.4%**; confidence: **90%**. Source: ISRO Bhuvan LULC mock verification.

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.22 ha	Primary driver - larger = higher score
Land Classification	UNVERIFIED ZONE	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	January 2025 → January 2026	Change detection window
Final Score	41.0/100	Severity: MEDIUM

This zone received a MEDIUM score of 41.0/100 because the detected construction covers 0.22 hectares - between 0.2 and 1 hectare. This is a moderate satellite-detected change requiring human verification.

Land Classification Note: The land classification for this zone could not be verified against available zoning data. The flag is based solely on the magnitude of satellite-detected construction change. Ground verification is required to determine the applicable land use rules.

Satellite Evidence

The images below show the flagged location in January 2025 (before) and January 2026 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



January 2025 - Before Construction



January 2026 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.