

AutoSentinel

Unauthorized Construction Detection Report

Generated: 03 August 2026, 21:49 IST | Analysis period: 2019–2026
Area analysed: Custom scanned area (19.2250, 72.8452) to (19.2503, 72.8659)

Severity: MEDIUM | Risk Score: 59.0/100

Zone Details

Field	Value
Zone ID	live 66b61cc7 34
Coordinates	19.239764°N, 72.855437°E
Constructed Area	0.58 hectares (5,800 sq metres)
Severity Level	MEDIUM
Risk Score	59.0 / 100
Violation Type	POSSIBLE PERMIT VIOLATION
Bhuvan Land Classification	Protected ridge buffer
Bhuvan Overlap / Confidence	74.4% / Low
Bhuvan Data Source	No land-use polygon intersected
OSM Overlays	POSSIBLE PERMIT VIOLATION, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW
Legal Flags	POSSIBLE PERMIT VIOLATION, CONSTRUCTION ACTIVITY, ROAD BUFFER REVIEW
Risk Boost	27.5

Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Protected ridge buffer**; polygon overlap: **74.4%**; confidence: **Low**. Source: No land-use polygon intersected.

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.58 ha	Primary driver - larger = higher score
Land Classification	POSSIBLE PERMIT VIOLATION	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2026	Change detection window
Final Score	59.0/100	Severity: MEDIUM

This zone received a MEDIUM score of 59.0/100 because the detected construction covers 0.58 hectares - between 0.2 and 1 hectare. This is a moderate satellite-detected change requiring human verification.

Land Classification Note: The detected change requires a land-use and permit review against available zoning data. Ground inspection is required to determine the applicable land use rules.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2026 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2026 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.