

Severity: MEDIUM | Risk Score: 42.5/100

### Zone Details

| Field                       | Value                                                     |
|-----------------------------|-----------------------------------------------------------|
| Zone ID                     | live_6bb03b35_360                                         |
| Coordinates                 | 28.211155°N, 77.102665°E                                  |
| Constructed Area            | 0.25 hectares (2,500 sq metres)                           |
| Severity Level              | MEDIUM                                                    |
| Risk Score                  | 42.5 / 100                                                |
| Violation Type              | UNVERIFIED ZONE                                           |
| Bhuvan Land Classification  | Unknown                                                   |
| Bhuvan Overlap / Confidence | 84.4% / Low                                               |
| Bhuvan Data Source          | No land-use polygon intersected                           |
| OSM Overlays                | PROTECTED_LAND, CONSTRUCTION_ACTIVITY, ROAD_BUFFER_REVIEW |
| Legal Flags                 | PROTECTED_LAND, CONSTRUCTION_ACTIVITY, ROAD_BUFFER_REVIEW |
| Risk Boost                  | 30.5                                                      |

### Bhuvan Land-use Verification

The zone was checked against the available ISRO Bhuvan-compatible land-use layer. Dominant classification: **Unknown**; polygon overlap: **84.4%**; confidence: **Low**. Source: No land-use polygon intersected.

### How the Risk Score Was Calculated

| Scoring Factor        | Value            | Contribution                           |
|-----------------------|------------------|----------------------------------------|
| Construction Area     | 0.25 ha          | Primary driver - larger = higher score |
| Land Classification   | UNVERIFIED ZONE  | Determines violation severity          |
| NDBI Change Magnitude | > 0.15 threshold | Confirms built-up area increase        |
| Time Period           | 2024 → 2025      | Change detection window                |
| Final Score           | 42.5/100         | Severity: MEDIUM                       |

This zone received a MEDIUM score of 42.5/100 because the detected construction covers 0.25 hectares - between 0.2 and 1 hectare. This is a moderate satellite-detected change requiring human verification.

Land Classification Note: The land classification for this zone could not be verified against available zoning data. The flag is based solely on the magnitude of satellite-detected construction change. Ground verification is required to determine the applicable land use rules.

### Satellite Evidence

The images below show the flagged location in 2024 (before) and 2025 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2024 - Before Construction



2025 - After Construction

---

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.