

■ Severity: MEDIUM | Risk Score: 76.5/100

Zone Details

Field	Value
Zone ID	live_3e6d34d7_0
Coordinates	19.406354°N, 72.768979°E
Constructed Area	0.93 hectares (9,300 sq metres)
Severity Level	MEDIUM
Risk Score	76.5 / 100
Violation Type	UNVERIFIED ZONE

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.93 ha	Primary driver - larger = higher score
Land Classification	UNVERIFIED ZONE	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	4-year change window
Final Score	76.5/100	Severity: MEDIUM

This zone received a MEDIUM score of 76.5/100 because the detected construction covers 0.93 hectares - between 0.2 and 1 hectare. This is a moderate unauthorized structure that warrants scheduled inspection.

Land Classification Note: The land classification for this zone could not be verified against available zoning data. The flag is based solely on the magnitude of satellite-detected construction change. Ground verification is required to determine the applicable land use rules.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

Recommended Action

Schedule inspection

1. Add to inspection queue for next available field officer visit.
2. Check online permit records before physical inspection.
3. Issue advisory notice if minor violations found.

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.