

■ Severity: HIGH | Risk Score: 72/100

Zone Details

Field	Value
Zone ID	live_test
Coordinates	19.400000°N, 72.800000°E
Constructed Area	1.20 hectares (12,000 sq metres)
Severity Level	HIGH
Risk Score	72 / 100
Primary Violation	AGRICULTURAL LAND

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	1.20 ha	Primary driver — larger = higher score
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	4-year change window
Land Classification	AGRICULTURAL LAND	Determines violation severity
Final Score	72/100	Severity: HIGH

This zone received a HIGH score of 72/100 because the detected construction covers 1.2 hectares — between 1 and 5 hectares. This scale of development on unverified land indicates significant unauthorized construction activity.

Land Classification Note: The construction location falls on land classified as agricultural. Converting agricultural land to non-agricultural use without Maharashtra government permission violates the Maharashtra Land Revenue Code. The construction intersects a mapped water body or wetland. Construction in these areas is prohibited under CRZ and water body protection regulations.

Land Use & Legal Context

Primary violation category: AGRICULTURAL LAND

Matched legal layers: AGRICULTURAL LAND, WATER BODY ENCROACHMENT

Site classification summary: this zone is assessed for agricultural land use, water body proximity, forest-zone overlap, or other protected/restricted land categories.

For each detected area, the enforcement authority should verify the exact cadastral and land-use status on the ground before issuing notices or penalties.

Detailed findings:

- AGRICULTURAL LAND: The construction location falls on land classified as agricultural. Converting agricultural land to non-agricultural use without Maharashtra government permission violates the Maharashtra Land Revenue Code.
- WATER BODY ENCROACHMENT: The construction intersects a mapped water body or wetland. Construction in these areas is prohibited under CRZ and water body protection regulations.

Satellite Evidence

Satellite image crops are not available for this zone. Images are pre-generated for Critical severity zones only. Use the AutoSentinel dashboard to view live satellite thumbnails for this location.

Recommended Action

Schedule inspection

1. Schedule ground inspection within 48 hours.
2. Verify building permit status with local municipal authority.
3. Issue notice to owner if construction is found to be unauthorized.
4. Escalate to CRITICAL if structure is found on protected land.

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.