

Severity: MEDIUM | Risk Score: 86.0/100

Zone Details

Field	Value
Zone ID	live_802ac3b2_56
Coordinates	19.298052°N, 72.965704°E
Constructed Area	0.42 hectares (4,200 sq metres)
Severity Level	MEDIUM
Risk Score	86.0 / 100
Violation Type	RAILWAY BUFFER VIOLATION
OSM Overlays	RAILWAY_BUFFER_VIOLATION, RIVER_BUFFER_VIOLATION, INDUSTRIAL_ZONE_A
Legal Flags	RAILWAY_BUFFER_VIOLATION, RIVER_BUFFER_VIOLATION, INDUSTRIAL_ZONE_A
Risk Boost	35.0

How the Risk Score Was Calculated

Scoring Factor	Value	Contribution
Construction Area	0.42 ha	Primary driver - larger = higher score
Land Classification	RAILWAY BUFFER VIOLATION	Determines violation severity
NDBI Change Magnitude	> 0.15 threshold	Confirms built-up area increase
Time Period	2019 → 2023	Change detection window
Final Score	86.0/100	Severity: MEDIUM

This zone received a MEDIUM score of 86.0/100 because the detected construction covers 0.42 hectares - between 0.2 and 1 hectare. This is a moderate satellite-detected change requiring human verification.

Land Classification Note: Land classification pending verification.

Satellite Evidence

The images below show the flagged location in 2019 (before) and 2023 (after). Visible change in land cover - new grey/brown built-up area replacing green or open land - confirms the satellite detection.



2019 - Before Construction



2023 - After Construction

DISCLAIMER: This report is auto-generated by AutoSentinel using satellite remote sensing and should be treated as a preliminary flag for human review. Satellite detection is based on NDBI change analysis of Sentinel-2 imagery (10m resolution) and may include false positives due to legitimate permitted construction not reflected in available zoning data. Final enforcement decisions must be made by authorized municipal officers following ground verification.