

INSPECTION REPORT

Machine ID: MX-01

Inspection Date: 03 October 2026

Measured Operating Temperature: 72°C

Vibration Level: Medium

Observed Condition: Machine operating normally.

Inspector Recommendation: Continue monitoring temperature and vibration.