Durga visarjan 2026 · Ghat risk brief

For the BMC officer planning Durga visarjan · 9 days to Tuesday 20 October 2026

Based on MPPCB visarjan water tests 2023–2025 at 7 Bhopal ghats, compared with the CPCB outdoor-bathing (Class B) limits.

⚠ **2 ghats need action now, 3 are high risk and 2 moderate. No ghat met every bathing limit.**

#	Ghat	Level	Action	Main reason	Tests
1	**Bairagarh (Sant Hirdaram) kund**	Act now · 57.1	**Aerate + send test team**	Oxygen fell to 0 mg/l in 4 tests. No fish can live at 0.	13/18
2	**Malikhedi kund**	Act now · 41.8	**Aerate + send test team**	Oxygen fell as low as 0.6 mg/l in 1 test, far below the minimum of 5.	13/18
3	**Shahpura lake ghat**	High · 34.8	**Aerate during and after**	Oxygen was below the bathing minimum of 5 mg/l in 5 of 18 tests.	18/18
4	**Rani Kamlapati ghat / Kamla Park kund**	High · 33.4	**Aerate during and after**	Oxygen was below the bathing minimum of 5 mg/l in 6 of 18 tests.	18/18
5	**Khatlapura ghat**	High · 31.3	**Aerate during and after**	Oxygen was below the bathing minimum of 5 mg/l in 8 of 18 tests.	18/18
6	**Hathaikheda dam / kund**	Moderate · 22.3	**Extra cleaning + re-test**	Oxygen stayed at or above 5 mg/l in all 18 tests (lowest 5.1).	18/18
7	**Prempura ghat**	Moderate · 16.8	**Aerate during and after**	Oxygen was below the bathing minimum of 5 mg/l in 3 of 18 tests.	18/18

Test on 20 October: Bairagarh (Sant Hirdaram) kund, Malikhedi kund have no Durga 2025 test. Missing is not clean.

All 7 ghats broke the BOD limit. Oxygen was below 5 mg/l in 42 of 116 readings and fell to 0 four times, all at Bairagarh.

What this does not cover

- No health claims. The reports test no bacteria (coliform), so the tool compares readings with CPCB limits and says nothing about illness.
- Bairagarh and Malikhedi have no Durga 2025 table and were tested only during Ganesh 2025 immersion. Their ranks rest on 13 of 18 tests.
- The NGT has banned immersion in the Upper and Lower Lakes and BMC is building new ghats (Free Press Journal, 26 Feb 2026). Lake ghats here may not be used this year; their readings still describe the lake water.
- Blank, _, * and ** mean not sampled. They show as missing and never count as clean. BDL means below detection: very low, not zero.
- "Rani Kamlapati ghat / Kamla Park kund" may be two places: Ganesh tables say Kamla Park kund, Durga tables say Lower Lake ghat.
- The score is a planning aid for where to act first. It is not a legal finding of compliance.

Every number above links to its MPPCB report page in प्राण-वायु.

दुर्गा विसर्जन 2026 · घाट जोखिम सारांश

दुर्गा विसर्जन की योजना बनाने वाले नगर निगम अधिकारी हेतु · मंगलवार, 20 अक्टूबर 2026 तक 9 दिन

भोपाल के 7 घाटों पर 2023–2025 की MPPCB विसर्जन जल-जाँच पर आधारित, CPCB खुले-स्नान (श्रेणी B) सीमाओं से तुलना।

⚠ **2 घाटों पर तुरंत कार्य ज़रूरी, 3 उच्च जोखिम और 2 मध्यम। कोई भी घाट सभी स्नान-मानकों पर खरा नहीं उतरा।**

#	घाट	स्तर	कार्य	मुख्य कारण	जाँचें
1	**बैरागढ़ (संत हिरदाराम) कुंड**	तुरंत कार्य · 57.1	**एरेटर लगाएँ + जाँच दल भेजें**	4 जाँचों में ऑक्सीजन 0 mg/l तक गिरी। 0 पर कोई मछली जीवित नहीं रह सकती।	13/18
2	**मालीखेड़ी कुंड**	तुरंत कार्य · 41.8	**एरेटर लगाएँ + जाँच दल भेजें**	1 जाँचों में ऑक्सीजन 0.6 mg/l तक गिरी, जो न्यूनतम 5 से बहुत कम है।	13/18
3	**शाहपुरा झील घाट**	उच्च · 34.8	**विसर्जन के दौरान और बाद एरेटर**	18 में से 5 जाँचों में ऑक्सीजन स्नान-मानक 5 mg/l से कम थी।	18/18
4	**रानी कमलापति घाट / कमला पार्क कुंड**	उच्च · 33.4	**विसर्जन के दौरान और बाद एरेटर**	18 में से 6 जाँचों में ऑक्सीजन स्नान-मानक 5 mg/l से कम थी।	18/18
5	**खटलापुरा घाट**	उच्च · 31.3	**विसर्जन के दौरान और बाद एरेटर**	18 में से 8 जाँचों में ऑक्सीजन स्नान-मानक 5 mg/l से कम थी।	18/18
6	**हथाईखेड़ा डैम / कुंड**	मध्यम · 22.3	**अतिरिक्त सफ़ाई + पुनः जाँच**	सभी 18 जाँचों में ऑक्सीजन 5 mg/l या अधिक रही (न्यूनतम 5.1)।	18/18
7	**प्रेमपुरा घाट**	मध्यम · 16.8	**विसर्जन के दौरान और बाद एरेटर**	18 में से 3 जाँचों में ऑक्सीजन स्नान-मानक 5 mg/l से कम थी।	18/18

⚗ **20 अक्टूबर को जाँच करें: बैरागढ़ (संत हिरदाराम) कुंड, मालीखेड़ी कुंड की दुर्गा 2025 जाँच नहीं है। जाँच न होना साफ़ होना नहीं है।**

सभी 7 घाटों पर BOD सीमा टूटी। 116 में से 42 रीडिंग में ऑक्सीजन 5 mg/l से कम थी और चार बार 0 तक गिरी, सभी बैरागढ़ में।

यह किन बातों को नहीं दर्शाता

- स्वास्थ्य संबंधी कोई दावा नहीं। रिपोर्टों में बैक्टीरिया (कोलीफ़ॉर्म) की जाँच नहीं है, इसलिए यह केवल रीडिंग की CPCB सीमाओं से तुलना करता है, बीमारी के बारे में कुछ नहीं कहता।
- बैरागढ़ और मालीखेड़ी की दुर्गा 2025 की तालिका नहीं है, और गणेश 2025 में केवल विसर्जन के दौरान जाँच हुई। इनका क्रम 18 में से 13 जाँचों पर आधारित है।
- NGT ने बड़े और छोटे तालाब में विसर्जन पर रोक लगाई है और नगर निगम नए घाट बना रहा है (फ़्री प्रेस जर्नल, 26 फ़रवरी 2026)। यहाँ के तालाब-घाट इस वर्ष उपयोग में न हों, फिर भी इनकी रीडिंग तालाब के पानी की स्थिति बताती हैं।
- खाली, _, * और ** का अर्थ है नमूना नहीं लिया गया। इन्हें अनुपलब्ध दिखाया जाता है, कभी साफ़ नहीं गिना जाता। BDL का अर्थ है पहचान-सीमा से कम: बहुत कम, शून्य नहीं।
- "रानी कमलापति घाट / कमला पार्क कुंड" दो स्थान हो सकते हैं: गणेश तालिकाओं में कमला पार्क कुंड, दुर्गा तालिकाओं में लोअर लेक घाट लिखा है।
- अंक यह तय करने का साधन है कि पहले कहाँ कार्य करें। यह अनुपालन का कानूनी निष्कर्ष नहीं है।

प्राण-वायु में ऊपर की हर संख्या MPPCB रिपोर्ट के पृष्ठ से जुड़ी है।